



AUDI Q7: 1287-MTC

Vinnumber:	WAUZZZ4M5RD015305	Versionname:	S line plus 55 TFSIe 280kW quattro tip todoterreno 280kW 5P automática
First Registrationdate:	22/07/2024	Fiscalpower:	
Expertise Mileage:	40145	Power Kw:	
Bodytype:	SUV	Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	No		
Category:	Passenger Car		
Registration Certificate Car (BE):	No		

Options

Number of keys total	2	Radio
Number keys remote	2	Seats electric F L
GPS big screen color		Seats electric F R
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Headlight sprinkler
Steering wheel multifunctional		Front parking sensors
Steering wheel leather		Rear parking sensors
Seats F heated		Roof bar alu
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

285/40/21/109 Y				
Summer tyres:	Fr.L.	Pirelli: 0 mm	Fr.R.	Pirelli: 0 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm
Tyre profile depth FL				0.0
Tyre profile depth FR				0.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				285/40 R 21 109 Y
Tyre size FR				285/40 R 21 109 Y
Tyre size RL				285/40 R 21 109 Y
Tyre size RR				285/40 R 21 109 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Repair kit	No
Number of charging cables (rapid charge)	1

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Tyre FL, Worn, Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Forfeit



Tyre FR, Worn, Acceptable



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror base R, Scratch(es), Paint



Door FR, Scratch(es), Acceptable



Door RR, Scratch(es), Repair and paint (complete)



Door trim RR, Scratch(es), Repair and paint (complete)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Tyre repair kit, Missing, Repair/replace (lump sum)



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Bumper spoiler Rear, Scratch(es), Paint



Tyres, No damage, Check



