



Mercedes A:

Vinnumber:	W1K1771841J323502	Versionname:	
First Registrationdate:	25/08/2021	Fiscalpower:	
Expertise Mileage:	76203	Power Kw:	
Bodytype:		Body colour	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2423
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	4978.0		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

205/60/16/92 H			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R. Continental: 5 mm
	Re.L.	Continental: 6 mm	Re.R. Continental: 6 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			6.0
Tyre profile depth RR			6.0
Tyre size FL			205/60 R 16 92 H
Tyre size FR			205/60 R 16 92 H
Tyre size RL			205/60 R 16 92 H
Tyre size RR			205/60 R 16 92 H
Tyre type FL			Winter
Tyre type FR			Winter
Tyre type RL			Winter
Tyre type RR			Winter
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	853,24
-------------------	--------

Bumper F, Dent(s) and scratch(es), Repair and paint (complete)	296,58
--	--------




Bonnet, Dent(s), Acceptable 0,00




Windscreen moulding, Scratch(es), Acceptable 0,00



Step L, Scratch(es), Acceptable 0,00



Wing RL, Scratch(es), Acceptable 0,00



Roof pillar L, Dent(s), Paintless dent repair 95,47



Boot carpet, Stain, Cleaning 29,16



Bumper trim R, Crack, Replace 283,70



Bumper R, Dent(s) and scratch(es), Spot repair 148,33



Tailgate / Boot, Dent(s), Acceptable

0,00



Door RR, Dent(s) and scratch(es), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00

