



RENAULT KANGOO FURGÓN: 2518-MRR

Vinnumber:	VF1RFK00572475920	Versionname:	L1 1.5 Blue dCi 70kW (95CV) furgón derivado de turismo 70kW 4P manual
First Registrationdate:	27/05/2024	Fiscalpower:	
Expertise Mileage:	87538	Power Kw:	
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	2		
Number head rests:	2		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Light Commercial Vehicle		
Registration Certificate Car (BE):	No		

Options

Number of keys total	3	Radio
Number keys remote	3	Luggage cover
Windows electric F		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

	195/65/15/95 H			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 95 H
Tyre size FR				195/65 R 15 95 H
Tyre size RL				195/65 R 15 95 H
Tyre size RR				195/65 R 15 95 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Registration document, Missing, Repair/replace (lump sum)



Bumper F, Scratch(es), Paint



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace



Internal boot lining R, Scratch(es), Replace




Internal boot lining L, Broken, Replace



Internal boot lining R, Crack, Replace



Tyres, No damage, Check



Roof, Dent(s), Repair and paint (complete)

