



### CITROËN BERLINGO: EZ-260-VC

Vinnumber:	<b>VF77DBHW6JJ645241</b>	Versionname:	<b>CITROËN BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)</b>
First Registrationdate:	<b>20/08/2018</b>	Fiscalpower:	
Expertise Mileage:	<b>189944</b>	Power Kw:	<b>55</b>
Bodytype:	<b>Transporter</b>	Body colour:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Interior colour:	<b>Black</b>
Fueltype:	<b>Diesel</b>	Type of rims (mounted):	<b>Steel</b>
Engine functioning:	<b>Yes</b>	Dashboard color:	<b>Black</b>
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Type of rims (mounted):	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		

### Options

Number of keys total	<b>2</b>	Tow bar	
Number keys remote	<b>2</b>	Radio	
Windows electric F		Rear parking sensors	
Cruise Control		Sliding door right-side	
Type of climate control	<b>Manual climate control</b>	Seat cover lining	<b>Lining Other</b>

### Tyres

<b>195/70/15/102 S</b>				
Summer tyres:	Fr.L.	<b>Other: 35%</b>	Fr.R.	<b>Other: 25%</b>
	Re.L.	<b>Other: 20%</b>	Re.R.	<b>Other: 20%</b>
Tyre profile depth FL				<b>6.0</b>
Tyre profile depth FR				<b>6.5</b>
Tyre profile depth RL				<b>7.0</b>
Tyre profile depth RR				<b>7.0</b>
Tyre size FL				<b>195/70 R 15 102 S</b>
Tyre size FR				<b>195/70 R 15 102 S</b>
Tyre size RL				<b>195/70 R 15 102 S</b>
Tyre size RR				<b>195/70 R 15 102 S</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>263</b>
Tyre make FR				<b>263</b>
Tyre make RL				<b>263</b>
Tyre make RR				<b>263</b>

### Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Inner door sill FR, Dent(s) and scratch(es), Repair and paint (complete)



Inner door sill FL, Scratch(es), Paint



Door seal FL, Tear, Replace



Steering wheel, Worn, Repair/replace (lump sum)



Gear shift lever knob, Broken, Replace



Door panel FL, Scratch(es), Replace



Dashboard, Scratch(es), Replace



Dashboard, Scratch(es), Replace



Door panel FR, Scratch(es), Replace



Interior trim, Scratch(es), Smart repair



Dashboard, Scratch(es), Replace



Interior, Dirty, Chemical cleaning



Remote ignition key, Worn, Repair/replace (lump sum)



Floor mat F, Tear, Repair/replace (lump sum)



Wheel arch cover FR, Broken, Replace



Wing FL, Dent(s), Repair and paint (complete)



Outside rear-view mirror base L, Broken, Replace



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door trim FL, Scratch(es), Replace



Door trim FL, Broken, Replace



Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Paint



Bumper F, Deformed / Strained, Replace



Bumper moulding FL, Missing, Replace



Bumper moulding FR, Missing, Replace



Bumper grille, Unclassped, Dismount/Mount



Grille, Scratch(es), Replace



Headlight R, Unclassped, Dismount/Mount



Side wall RR, Dent(s) and scratch(es), Repair and paint (complete)



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Scratch(es), Paint



Door trim FR, Scratch(es), Replace



Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace



Outside rear-view mirror glass R, Broken, Replace



Rear floor trunk, Rust, Paint



Rubber seal for boot lid, Tear, Replace



Rubber seal for boot lid, Tear, Replace



Door hinge RL top, Broken, Replace



Door hinge RR top, Broken, Replace



Door seal R, Unclipped, Dismount/Mount



Boot door lining R, Broken, Replace



Boot door lining L, Broken, Replace



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot door panel RR, Rust, Paint



Bumper R, Deformed / Strained, Replace



Bumper corner RL, Broken, Replace



Bumper corner RR, Scratch(es), Repair and paint (complete)



Roof, Chemical pollution, Paint



Other exterior parts, Tear, Acceptable



# Historique Maintenance

Immatriculation: **EZ-260-VC**Date de 1ère immatriculation: **20/08/2018**Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
10/03/2026	187.142	CLARA AUTOMOBILES	LAMPE RPLT
23/09/2025	175.071	CLARIS AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AV RPLT
	0		COURROIE DISTRIBUTION RPLT
	0		FILTRE CLIM RPLT
	0		KIT ACCESSOIRES RPLT
	0		DIVERS CLIM
	0		REVISION
	0		DIVERS ECHAPPEMENT
19/06/2025	166.887	CLARIS AUTOMOBILES	DIVERS ECHAPPEMENT
	0		LAMPE CODE AVD RPLT
26/03/2025	157.637	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
20/03/2025	157.597	CLARIS AUTOMOBILES	JOINT DE COUVRE CULASSE RPLT
	0		DIVERS ECHAPPEMENT
	0		BOITIER D EAU RPLT
	0		ELECTROVANNE DE TURBO RPLT
	0		TLG POUBELLE
	0		DIVERS MOTEUR
	0		BOITIER SERVITUDE INTELLIGENT BSI RPLT
31/10/2024	154.164	CLARIS AUTOMOBILES	DIVERS ELEC
	0		LIQUIDE DE FREIN
	0		DIVERS ECHAPPEMENT
	0		DIVERS CLIM
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		DISQUES PLAQUETTES AR RPLT
	0		ADBLUE
	0		COURROIE ACCESSOIRES RPLT
	0		DIVERS MOTEUR
	0		SERRURE RPLT
20/09/2024	152.727	DEKRA AUTOMOTIVE S.A	ANTIPOLLUTION
12/03/2024	138.468	CLARIS AUTOMOBILES	LAMPE AR RPLT
	0		RECYCLAGE

# Historique Maintenance

Immatriculation: **EZ-260-VC**

Date de 1ère immatriculation: **20/08/2018**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
	0		LAMPE RPLT
19/09/2023	129.700	CLARIS AUTOMOBILES	REVISION
	0		DIVERS CLIM
	0		DIVERS ECHAPPEMENT
	0		FILTRE CLIM RPLT
	0		COURROIE DISTRIBUTION RPLT
	0		LAMPE CODE AVD RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		BALAIS ESSUIE GLACE AV
	0		PLAQUETTES AR RPLT
30/05/2023	120.833	DEKRA AUTOMOTIVE S.A	CONTRE VISITE CT
26/04/2023	118.237	CLARIS AUTOMOBILES	CEINTURE DE SECURITE RPLT
	0		DIVERS
18/04/2023	117.328	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
25/01/2023	112.368	CLARIS AUTOMOBILES	BARRE STABILISATRICE RPLT
19/12/2022	109.152	CLARIS AUTOMOBILES	LAMPE CODE AVD RPLT
19/09/2022	96.393	CLARIS AUTOMOBILES	REVISION ET CLIM ET AIR ET CARBURANT
	0		DIVERS CLIM
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		DIVERS ECHAPPEMENT
	0		REVISION ET CLIM ET AIR ET CARBURANT
25/07/2022	96.393	CLARIS AUTOMOBILES	PLAQUETTES AV RPLT
21/07/2022	95.822	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
01/03/2022	86.505	CLARIS AUTOMOBILES	INJECTEUR ADBLUE RPLT
	0		LAMPE AR RPLT
	0		DIVERS MOTEUR
	0		COURROIE DISTRIBUTION RPLT
	0		FAP RPLT
	0		CAPTEURS DIVERS RPLT
	0		TUYAU ECHAPPEMENT RPLT
	0		FERMETURE DOSSIER TECHNIQUE

# Historique Maintenance

Immatriculation: **EZ-260-VC**

Date de 1ère immatriculation: **20/08/2018**

Modèle: **Citroen BERLINGO BlueHDi 75 BVM Club M VU [3P] bvm 5-75CH-5cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
28/02/2022	86.505	CLARIS AUTOMOBILES	DIVERS MOTEUR
	0		DIVERS ELEC
	0		FAP RPLT
22/02/2022	85.560	CLARIS AUTOMOBILES	DIVERS ELEC
	0		BATTERIE RPLT
22/09/2021	75.092	CLARIS AUTOMOBILES	PLAQUETTES AR RPLT
	0		BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		REVISION
07/10/2020	48.129	CLARIS AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		FILTRE CLIM RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		REVISION
	0		FILTRE A AIR RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
16/07/2019	17.341	CLARIS AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		REVISION