Audi

AUDI A4 AVANT (8WD)(05.2019->) 35 TDI BASIS HYBRIDATION LÉGÈRE 120 KW (MOTEUR 2,0 LITRE(S) - 120 KW 16V TDI) 4 PORTES

VIN: WAUZZZF4XNA009444



Description

Registration number 2BGQ182	**Registration date** 18/11/2021	**Odometer** 161667 km
Color Gris Terra Métallisé	**Year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1968	**Gearbox type** Automatic	**Engine type** Combustion
Fuel Type Diesel	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 120 KW		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

airbag passenger side deactivatable	sidebag front	Alternateur 130-200 A
immobilizer (electronic)	Audi connect (Emergency and Assistance System)	Audi music interface
transmission 7-speed - dual-clutch transmission S-tronic	body: 4-door	standard suspension
automatic air-conditioning system	radio-remote key	tire pressure control system
power steering electromechanical	brake discs rear (300 mm x 12 mm)	brake discs front (314 mm x 25 mm)
rear seat backrest split/folding (40:20:40)	light and rain sensor	electronic stability control (ESC)
window trim strips black	Longlife-Service	interior equipment decorative trim inserts diamond paint Silver gray
interior equipment decorative trim inserts accent parts in the instrument panel black matte	rear lights LED	turn signal lights LED in exterior mirror integrated
diesel particulate filter	refrigerant R 1234 YF	roof liner cloth
windshield washer jets heated	universal interface Bluetooth	wheelbase 3000 mm
tire repair kit	vehicle speed limiter	Mild-Hybrid-Technologie
Type of drive: front-wheel drive	multi-media Interface MMI basic plus / MMI radio plus	low emissions according to emission standard Euro 6d-TEMP
non-smoking package	windshield acoustic glass	bumper variant: base
reversible luggage compartment floor (cargo floor)	low-resistance tires	tire 205/60 R16 ..V
headlight base (LED - technology)	scuff rails with aluminium insert	model refinement
radio reception digital (DAB)	cruise control (cruise control)	urea tank (SCR) 12 liter
exterior mirror vehicle colour	exterior mirror electrically adjustable and heated	seat covers/upholstery: cloth Index
seats front manually adjustable	standard seats front	Isofix mounts for child seat
floor mats velours	head airbag system (Sideguard)	antilock braking system (ABS)
driver assistance system: City emergency braking function	SCR system (AdBlue technology)	start/stop system
trunk lining	daytime running lights LED	

Optional

center armrest front comfort equipment	parking aid front and rear, acoustic and optical with selective display (APS Plus)	Audi connect (web-based services)
Audi Smartphone Interface	roof rails (aluminium)	battery 68 Ah
rear lid open+close automatic (Hands-Free-Access system)	front camera (multi-functional camera windshield)	Moteur 2,0 litre(s) - 120 kW 16V TDI hybridation légère (DTNA)
multi-media Interface MMI Navigation Plus with MMI Touch	Driver Information System (DIS) (FIS) with colour display	Shine package
metallic paintwork	multi-media interface 2 x USB (type C) front and 2 x USB charging port (type C) center console rear	fuel tank: 54 liter
exterior mirror aspherical, left	exterior mirror convex, right	sound system DSP / Audi sound system
driver assistance system: start-up assistant (hold-assist)	pedestrian protection system	panoramic roof front electric, rear fixed
glazing rear darkened (Privacy Glass)	steering wheel (sport/leather - 3-spokes) with multiple function and shift function	brake calipers black painted (high-gloss)

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	16/09/2026	17/09/2026

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rear parcel shelf / -	Missing	Replace




002	Registration certficate2 / -	Missing	Replace



003	Roof / - Sunroof : Yes	Paint etching	Polishing





004	Bonnet / -	Dent	Acceptable



005	Bonnet / -	Paint etching	Polishing







All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

006	Wing / Front Left	Dent	Repair





007	Interior complete / -	Dirty	Cleaning





008	Door / Front Left	Dent	Acceptable



009	Door / Front Left	Dent	Acceptable



010	Door sill / Back Left	Dent	Acceptable



011	Wing / Back Left	Dent	Repair






All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

012	Interior tailgate lining / Back Trim material : Plastic	Scratched	Smart repair






013	Bumper / Back Painted : Yes	Dent	Repair







014	Bumper / Back Painted : No	Dent	Replace





015	Exhaust tip / Back Left Material : Metal	Non Compliant	Check





016	Door sill / Back Right	Dent	Repair




017	Door / Back Right	Dent	Acceptable



All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

018	Door handles / Front Right	Scratched	Acceptable



019	Rear-view mirror / Right	Scratched	Smart repair




020	Wing / Front Right	Scratched	Acceptable



021	Bumper / Front Painted : Yes	Dent	Repair










Loose Items

- [ ] Rear parcel shelf
- [x] Triangle
- [x] Refill tyre repair kit
- [x] Spare Key
- [x] Tyre repair kit complete
- [x] First aid kit
- [x] Conformity certificate
- [x] Towing hook
- [x] Compressor tyre repair kit
- [ ] Registration certificate owner
- [x] Registration certificate
- [x] Safety vest

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	GOODYEAR	205 / 60 / 16 / Summer	3 mm
Front Right	GOODYEAR	205 / 60 / 16 / Summer	3 mm
Back Left	GOODYEAR	205 / 60 / 16 / Summer	3 mm
Back Right	GOODYEAR	205 / 60 / 16 / Summer	3 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right


Odometer


Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Rear parcel shelf / - / Missing



Registration certficate2 / - / Missing



Roof / - / Paint etching



Roof / - / Paint etching



Roof / - / Paint etching



Bonnet / - / Dent



Bonnet / - / Paint etching



Bonnet / - / Paint etching



Bonnet / - / Paint etching



Wing / Front Left / Dent




Wing / Front Left / Dent



Wing / Front Left / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Interior complete / - / Dirty



Door / Front Left / Dent



Door / Front Left / Dent



Door sill / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Wing / Back Left / Dent



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Interior tailgate lining / Back / Scratched



Interior tailgate lining / Back / Scratched



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Exhaust tip / Back Left / Non Compliant



Exhaust tip / Back Left / Non Compliant



Exhaust tip / Back Left / Non Compliant



Door sill / Back Right / Dent



Door sill / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Back Right / Dent



Door handles / Front Right / Scratched



Rear-view mirror / Right / Scratched



Rear-view mirror / Right / Scratched



Wing / Front Right / Scratched



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.