

INSPECTION REPORT

End of contract

GENERAL INFO

File	310140
License plate	2AFV346
Vehicle identification number	WAUZZZGY3MA090495
Dossier	2020323092
Make	Audi A3 SB 30 TFSi 81kW Str.
Mileage	58111
First registration	22/03/2021
client availability date	10/04/2026
inspectionDate	16/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
222	Side View Mirror Right // Painting	N
12	Bumper Front // Smart Repair Large	Y
136	Bumper Rear // Polish	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
230	Wing Front right // Smart Repair Small	N
275	Bumper Front / Grid Right / Replace	Y

Damage Pictures



Wing Front right // Smart Repair Small-dent



Door Front Right // Painting-scratch



Door Rear Right // Polish-scratch



Bumper Rear // Polish-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right // Painting-scratch