



BMW X1

Vinnumber:	WBA71AB0905V32359	Versionname:	
First Registrationdate:	13/05/2022	Fiscalpower:	
Expertise Mileage:	110718	Power Kw:	
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2205
Fueltype:	Hybrid Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

225/55/17/101 V				
Winter tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm
Tyre profile depth FL	5.0			
Tyre profile depth FR	5.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	225/55 R 17 101 V			
Tyre size FR	225/55 R 17 101 V			
Tyre size RL	215/55 R 17 101 V			
Tyre size RR	225/55 R 17 101 V			
Tyre type FL	Winter			
Tyre type FR	Winter			
Tyre type RL	Winter			
Tyre type RR	Winter			
Tyre make FL	2484			
Tyre make FR	2484			
Tyre make RL	2484			
Tyre make RR	2484			

Assistance equipment

Number of charging cables (normal)	1	
Number of charging cables (rapid charge)	1	
Total cost ex VAT		1688,59
Seat cover FL, Tear, Replace		560,77



Floor covering FL, Burned, Smart repair

116,69



Bumper F, Scratch(es), Spot repair

148,33



Door seal RL, Broken, Replace

114,56



Wing trim RL, Scratch(es), Replace

106,39



Door RL, Scratch(es), Spot repair

148,33



Alloy rim FL, Scratch(es), Acceptable

0,00



Boot lid covering R, Scratch(es), Smart repair

116,69



Bumper R, Dent(s), Spot repair

148,33



Alloy rim FR, Scratch(es), Repair and paint (complete)

133,03



Door FR, Dent(s), Paintless dent repair

95,47

