



## Mercedes GLA-Klasse (UKL): 2BUZ290

|                                   |                   |                        |                                                   |
|-----------------------------------|-------------------|------------------------|---------------------------------------------------|
| Vinnumber:                        | W1N2477861J374059 | Versionname:           | GLA250e Business Solution 1.3i 218pk/cv 5p 8G-DCT |
| First Registrationdate:           | 1/04/2022         | Fiscalpower:           |                                                   |
| Expertise Mileage:                | 81390             | Power Kw:              | 118                                               |
| Bodytype:                         |                   | Type of rims (mounted) | Aluminium                                         |
| Gearbox:                          | Automatic         |                        |                                                   |
| Transmission:                     |                   |                        |                                                   |
| Fueltype:                         | Hybrid Petrol     |                        |                                                   |
| Maintenance                       | OK                |                        |                                                   |
| Battery functioning               | Yes               |                        |                                                   |
| Type of rims (mounted)            | Aluminium         |                        |                                                   |
| Certificate of Conformity         | Yes               |                        |                                                   |
| Category                          | Passenger Car     |                        |                                                   |
| Registration Certificate Car (BE) | Yes               |                        |                                                   |

## Options

|                          |                     |                 |            |
|--------------------------|---------------------|-----------------|------------|
| Number of keys total     | 2                   | Luggage cover   |            |
| GPS                      |                     | Type of Tow bar | No Tow bar |
| Type of Maintenance book | Digital maintenance |                 |            |
| Type of GPS storage      | HD                  |                 |            |

## Tyres

| 215/65/17/99 V        |       |                   |       |                   |
|-----------------------|-------|-------------------|-------|-------------------|
| Summer tyres:         | Fr.L. | Continental: 6 mm | Fr.R. | Continental: 6 mm |
|                       | Re.L. | Continental: 6 mm | Re.R. | Continental: 6 mm |
| Tyre profile depth FL |       |                   |       | 6.0               |
| Tyre profile depth FR |       |                   |       | 6.0               |
| Tyre profile depth RL |       |                   |       | 6.0               |
| Tyre profile depth RR |       |                   |       | 6.0               |
| Tyre size FL          |       |                   |       | 215/65 R 17 99 V  |
| Tyre size FR          |       |                   |       | 215/65 R 17 99 V  |
| Tyre size RL          |       |                   |       | 215/65 R 17 99 V  |
| Tyre size RR          |       |                   |       | 215/65 R 17 99 V  |
| Tyre type FL          |       |                   |       | Summer            |
| Tyre type FR          |       |                   |       | Summer            |
| Tyre type RL          |       |                   |       | Summer            |
| Tyre type RR          |       |                   |       | Summer            |
| Tyre make FL          |       |                   |       | 256               |
| Tyre make FR          |       |                   |       | 256               |
| Tyre make RL          |       |                   |       | 256               |
| Tyre make RR          |       |                   |       | 256               |

## Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 1   |            |     |
| Number of charging cables (rapid charge) | 1   |            |     |

## Bumper spoiler F, Scratch(es), Acceptable



## Windscreen, Stone chip(s), Windscreen repair



Alloy rim FL polished, Chemical polution, Repair and paint (complete)



Door RL, Dent(s), Paintless dent repair



Alloy rim RL polished, Chemical polution, Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR polished, Chemical polution, Repair and paint (complete)



Alloy rim FR polished, Chemical polution, Repair and paint (complete)





Mirror side repeater R, Scratch(es), Replace



|                |                                                            |
|----------------|------------------------------------------------------------|
| Kenteken       | 2BUZ290                                                    |
| Merk Model     | Mercedes GLA250e Business Solution 1.3i 218pk/cv 5p 8G-DCT |
| Brandstofsoort | Benzine                                                    |
| Datum deel1    | 4/1/22                                                     |

| Datum reparatie | Kilometerstand | Reparatie omschrijving          | Bewerking        |
|-----------------|----------------|---------------------------------|------------------|
| 12/10/25        | 71,884         | bougie                          | Vervangen        |
| 12/10/25        | 71,884         | klein materiaal                 |                  |
| 12/10/25        | 71,884         | luchtfilter                     | Vervangen        |
| 12/10/25        | 71,884         | mercedes assyst b               | Uitvoeren        |
| 12/10/25        | 71,884         | remvloeistof                    | Vervangen        |
| 12/10/25        | 71,884         | ruitwisserrubber achter         | Vervangen        |
| 12/10/25        | 71,884         | ruitwisserrubber vooraan        | Vervangen        |
| 12/17/24        | 56,207         | mercedes assyst a               | Uitvoeren        |
| 4/12/24         | 45,161         | ruitwisserrubber achter         | Vervangen        |
| 4/12/24         | 45,161         | ruitwisserrubber vooraan        | Vervangen        |
| 4/12/24         | 45,161         | ruitwisservloeistof             | Bijvullen/-laden |
| 2/13/24         | 41,692         | mercedes assyst b               | Uitvoeren        |
| 2/13/24         | 41,692         | remvloeistof                    | Vervangen        |
| 2/13/24         | 41,692         | stoffilter (motor compartiment) | Vervangen        |
| 3/24/23         | 17,069         | mercedes assyst a               | Uitvoeren        |