



NISSAN QASHQ

| | | | |
|------------------------------------|--------------------------|-------------------------|---------------------------|
| Vinnumber: | SJNFAAJ11U2421306 | Versionname: | dCi 115 N-Connecta |
| First Registrationdate: | 14/01/2019 | Fiscalpower: | |
| Expertise Mileage: | 148433 | Power Kw: | 85 |
| Bodytype: | | Body colour: | White |
| Gearbox: | MAN 6 VIT | Type of rims (mounted): | Aluminium |
| Transmission: | | Parking lot: | 2401 |
| Fueltype: | Diesel | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--------------------------|
| Number of keys total | 2 | Panoramic roof | |
| Cruise Control | | Luggage cover | |
| Steering wheel multifunctional | | Front parking sensors | |
| Radio multimedia | | Rear parking sensors | |
| Type of headlighting | Headlighting Halogen | Type of Tow bar | Tow bar removable |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

Tyres

| 215/55/18/92 H | | | | |
|-----------------------|-------|--------------------------|-------|-------------------------|
| Summer tyres: | Fr.L. | Continental: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Michelin: 5 mm |
| Tyre profile depth FL | | | | 5.0 |
| Tyre profile depth FR | | | | 5.0 |
| Tyre profile depth RL | | | | 5.0 |
| Tyre profile depth RR | | | | 5.0 |
| Tyre size FL | | | | 215/55 R 18 92 H |
| Tyre size FR | | | | 215/55 R 18 92 H |
| Tyre size RL | | | | 215/55 R 18 92 H |
| Tyre size RR | | | | 215/55 R 18 92 H |
| Tyre type FL | | | | Summer |
| Tyre type FR | | | | Summer |
| Tyre type RL | | | | Summer |
| Tyre type RR | | | | Summer |
| Tyre make FL | | | | 256 |
| Tyre make FR | | | | 261 |
| Tyre make RL | | | | 256 |
| Tyre make RR | | | | 261 |

Assistance equipment

| | | | |
|--|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Number of charging cables (normal) | 0 | | |
| Number of charging cables (rapid charge) | 0 | | |

| | |
|--------------------------------|----------------|
| Total cost ex VAT | 1092,43 |
| Seat cover FL, Stain, Cleaning | 29,16 |



Alloy rim RL polished, Scratch(es), Acceptable 0,00



Door FL, Dent(s) and scratch(es), Repair and paint (complete) 445,79



pair and paint (complete) 296,58



B, Smart repair 116,69



Rear window, Scratch(es), Replace 0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Wing RR, Dent(s) and scratch(es), Acceptable 0,00



Alloy rim RR polished, Rust, Acceptable 0,00

