

BMW X6

Vehicle reference:

WBA11EY0309V90853

Body type:

Estate

Gearbox type:

Automatic

Engine size:

2993 cm³

Fuel type:

Electric, Diesel

Combustion engine power:

210 kW / 286 hp

Drive:

AWD

Quick check


Damage


This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.


Import


Not a private import

Legend

 No issues reported or indicated

 Valuable Information

 Requires attention

 Data unavailable

Damage overview

10/2025

Affected area



Reported in
Italy

Damage type/cause
Not available

Damage severity:



Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Mileage Check

Last odometer reading

77,632 km

Reported on: 2025-10-07

Average mileage


52,668 km/year

Average mileage for similar cars

22,673 km/year

Date
06/2025

Mileage
61,624 km



— Mileage readings of this car - - - - Average mileage for similar cars



No issues indicated: The reported odometer readings have a logical progression. There are no indications of manipulation. Unfortunately, we cannot guarantee this, so we always recommend critically questioning the odometer readings, e.g. on signs of wear, the number of oil changes, or the average kilometers driven per year.

Owners BETA



Owner(s) in Italy

Purchase year: **2024**

Damage reported on: **10/2025**

Technical details

Engine and performance

Fuel type

Electric, Diesel

Combustion engine power

210 kW / 286 hp

Environment and consumption

EU emission standard

Euro 6

Weight

Gross vehicle weight

3,050 kg

Other information

European vehicle category

M1

EU standard code

e1*07/46*2020*09

Number of doors

4

Number of seats

5

History information

Date

Mileage

Event

2024-04-17

Registered in Italy

10/2024

25,628 km

Odometer reading reported

02/2025	50,781 km	Odometer reading reported
---------	-----------	----------------------------------

06/2025	61,624 km	Odometer reading reported
---------	-----------	----------------------------------

10/2025	77,632 km	Odometer reading reported
---------	-----------	----------------------------------

10/2025		Damage reported in Italy
---------	--	---------------------------------

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

Carfax glossary

Average Mileage

Average Mileage is not the actual odometer reading for this car, but an estimate of how many kilometers an average car of this make, model, fuel type and age would be expected to have if used solely for personal use. The actual mileage for this particular car will indicate if it has been driven more or less than average and may be a factor to help you determine its value

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our [Terms and conditions](#).