



OPEL INSIGNIA SPORTS

Vinnnumber:	W0VZM8EN0M1017191	Versionname:	1.5 Turbo D S/S 90kW Business Edition
First Registrationdate:	22/04/2021	Fiscalpower:	
Expertise Mileage:	127233	Power Kw:	90
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3723
Fueltype:	Diesel		
Maintenance:	NOT OK		
Maintenance:	0%		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Sun Roof electric	
Cruise Control:		Panoramic roof	
Steering wheel multifunctional:		Luggage cover	
Seats F heated:		Front parking sensors	
Radio multimedia:		Rear parking sensors	
Type of headlighting:	Headlighting LED	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection

Tyres

	215/55/17/94 V			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL:				5.0
Tyre profile depth FR:				5.0
Tyre profile depth RL:				5.0
Tyre profile depth RR:				5.0
Tyre size FL:				215/55 R 17 94 V
Tyre size FR:				215/55 R 17 94 V
Tyre size RL:				215/55 R 17 94 V
Tyre size RR:				215/55 R 17 94 V
Tyre type FL:				Summer
Tyre type FR:				Summer
Tyre type RL:				Summer
Tyre type RR:				Summer
Tyre make FL:				261
Tyre make FR:				261
Tyre make RL:				261
Tyre make RR:				261

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	634,52
Service, Maintenance, Check:	0,00



Floor covering FR, Stain, Cleaning 29,16



Bonnet, Scratch(es), Acceptable 0,00



Bumper F, Scratch(es), Spot repair 148,33



Bumper F, Repaired, Acceptable 0,00



Alloy rim FL, Scratch(es), Repair and paint (complete) 133,03



Alloy rim RL, Scratch(es), Repair and paint (complete) 133,03



Door RL, Dent(s), Acceptable 0,00



Wing RL, Dent(s), Acceptable 0,00



Boot lid covering R, Dirty, Cleaning 29,16



Wing RR, Scratch(es), Polish 0,00



Door RR, Scratch(es), Polish 0,00



Wing RR, Repaired, Acceptable 0,00



Door FR, Scratch(es), Polish 0,00



Wing FR, Scratch(es), Polish 0,00



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete) 161,81



Alloy rim FR, Scratch(es), Acceptable 0,00



Side window trim FR, Scratch(es), Acceptable 0,00

