



### Audi

Vinn	<b>WAUZZZGY4MA136206</b>	Versionname:	
First Registrationdate:	<b>2/07/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>140711</b>	Power Kw:	
Bodytype:		Body colour	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted)	<b>Aluminium</b>
Transmission:		Parking lot	<b>1414</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted)	<b>Aluminium</b>		
Certificate of Conformity	<b>Yes</b>		
Category	<b>Passenger Car</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

### Options

Number of keys total	<b>2</b>	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	<b>No Tow bar</b>
Radio multimedia			
Type of headlighting	<b>Headlighting LED</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

### Limited Technical Inspection

### Tyres

<b>225/55/17/92 H</b>				
Summer tyres:	Fr.L.	<b>Goodyear: 5 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>225/55 R 17 92 H</b>
Tyre size FR				<b>225/55 R 17 92 H</b>
Tyre size RL				<b>225/55 R 17 92 H</b>
Tyre size RR				<b>225/55 R 17 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>259</b>
Tyre make FR				<b>259</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

### Assistance equipment

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>344,90</b>
Seat cover FL, Damaged, Acceptable	<b>0,00</b>



Alloy rim RL, Scratch(es), Repair and paint (complete)

133,03



Wheel cover RL, Missing, Replace

26,28



Wing RL, Dent(s), Acceptable

0,00



Door RL, Scratch(es), Acceptable

0,00



Alloy rim FL, Scratch(es), Acceptable

0,00



per R, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Wheel cover FR, Missing, Replace

26,28



Alloy rim RR, Scratch(es), Repair and paint (complete)

133,03



Wheel cover RR, Missing, Replace

26,28

