MACADAM







Mercedes CLA-Klasse (KKL): 2CLX614

Vinnumber:	**W1K1183861N322017**	Versionname:	**CLA250e Sedan Business Solution 1.3i 218pk/cv 4p 8G-DCT**
First Registrationdate:	**9/09/2022**	Fiscalpower:	
Expertise Mileage:	**72807**	Power Kw:	**118**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Plug-in Hybrid Petrol**		
Maintenance	**OK**		
Maintenance	**over 127 dagen**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Type of Tow bar	**No Tow bar**
GPS			
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/45/18/91 W**			
	Fr.L.	**Bridgestone: 3 mm**	Fr.R.	**Bridgestone: 3 mm**
	Re.L.	**Goodyear: 3 mm**	Re.R.	**Goodyear: 3 mm**

Tyre profile depth FL	**3.0**
Tyre profile depth FR	**3.0**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**225/45 R 18 91 W**
Tyre size FR	**225/45 R 18 91 W**
Tyre size RL	**225/45 R 18 95 W**
Tyre size RR	**225/45 R 18 95 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**
Number of charging cables (normal)	**0**		
Number of charging cables (rapid charge)	**1**		

Bonnet, Stone chip(s), Acceptable




Wing FL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable




Alloy rim FL polished, Scratch(es), Repair and paint (complete)







Charging cable (normal), Missing, Check



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)









Wing FR, Scratch(es), Acceptable










Door FR, Scratch(es), Acceptable




Alloy rim RR polished, Scratch(es), Acceptable





Onderhoudshistorie van: W1K1183861N322017

ALPHABET

Kenteken	2CLX614
Merk Model	Mercedes CLA250e Sedan Business Solution 1.3i 218pk/cv 4p 8G-DCT
Brandstofsoort	Benzine
Datum deel1	9/9/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
7/22/26	66,642	klein materiaal	
7/22/26	66,642	nazicht technische keuring	Uitvoeren
3/3/26	61,793	bougie	Vervangen
3/3/26	61,793	klein materiaal	
3/3/26	61,793	luchtfilter	Vervangen
3/3/26	61,793	mercedes assyst a	Uitvoeren
2/14/25	46,167	klein materiaal	
1/31/25	45,661	dakgel. smeren	Uitvoeren
1/31/25	45,661	klein materiaal	
1/31/25	45,661	mercedes assyst b	Uitvoeren
1/31/25	45,661	remvloeistof	Vervangen
10/2/23	25,011	mercedes assyst a	Uitvoeren