



PEUGEOT 208: FM-998-MM

Vinnumber:	VF3CCHMRPKW121211	Versionname:	208 Puretech 82 Active VP [5P] bvm 5-82CH-4cv (bi-corps)
First Registrationdate:	19/12/2019	Fiscalpower:	
Expertise Mileage:	87847	Power Kw:	
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Type of climate control	Manual climate control		

Tyres

	185/65/15/92 V			
Winter tyres:	Fr.L.	Bridgestone: 100%	Fr.R.	Bridgestone: 100%
	Re.L.	Bridgestone: 85%	Re.R.	Bridgestone: 100%
Tyre profile depth FL				0.1
Tyre profile depth FR				1.6
Tyre profile depth RL				2.4
Tyre profile depth RR				1.4
Tyre size FL				185/65 R 15 92 V
Tyre size FR				185/65 R 15 92 V
Tyre size RL				185/65 R 15 92 V
Tyre size RR				185/65 R 15 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Door seal FL, Tear, Replace



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Wheel cover FR, Broken, Replace



Door FL, Scratch(es), Paint



Bumper F, Scratch(es), Paint



Outer sill R, Dent(s), Repair and paint (complete)



Door RR, Dent(s), Repair and paint (complete)



Outside rear-view mirror base R, Broken, Replace



Outside rear-view mirror housing R, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **FM-998-MM** Date de 1ère immatriculation: **19/12/2019**

Modèle: **Peugeot 208 Puretech 82 Active VP [5P] bvm 5-82CH-4cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
23/03/2026	86.719	GARAGE MARCHAND	DIVERS CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
	0		REVISION ET CLIM
13/01/2026	85.038	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
15/07/2025	81.047	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
28/04/2025	78.879	GARAGE MARCHAND	FILTRE CLIM RPLT
	0		REVISION
	0		LIQUIDE DE FREIN
	0		DIVERS CLIM
	0		KIT DISTRIBUTION RPLT
	0		COURROIE ACCESSOIRES RPLT
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
07/03/2024	64.494	GARAGE MARCHAND	REVISION
31/01/2024	63.698	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
27/02/2023	52.984	GARAGE MARCHAND	REVISION
	0		BOITIER D ALLUMAGE RPLT
	0		FILTRE CLIM RPLT
	0		DISQUES PLAQUETTES AV RPLT
	0		FILTRE A AIR RPLT
17/10/2022	46.745	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS 4 SAISONS
28/02/2022	37.274	GARAGE MARCHAND	FILTRE CLIM RPLT
	0		REVISION
	0		LAMPE CODE AVD RPLT
25/11/2021	33.026	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS 4 SAISONS
12/02/2021	17.137	GARAGE MARCHAND	FILTRE CLIM RPLT
	0		REVISION