

2-EDF-562

2-EDF-562 · 530e Tour Business Pakket 2.0 292PS AT · 6 August 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-EDF-562	Fuel Type	Hybrid Gasoline
Manufacturer	BMW	VIN	WBA11CG030CP20493
Model	5-SERIE	Cylinder Capacity	1.998 ^{cm3}
Model Versions	530e Tour Business Pakket 2.0 292PS AT	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	04-09-2023
Body Type	5 door hatchback	Odometer	105.415 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Black
Production Year	2023	Number Headrests	4
KW	215		

Images





Accessories

ABS	Electrically adjustable driver's seat
Airbags	
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Seat heating
Electric rear windows	Steering wheel multifunction
Electric windows front	Steeringwheel - Heated


Condition

Condition exterior	Adequate	Maintenance Remarks	Bandenspanning controleren Oliepeil controleren Remvloeistof vervangen
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Hankook	245 mm	45 mm	18 inch	Summer
Rear Left	5 mm	Semperit	245 mm	45 mm	18 inch	All Season
Front Right	5 mm	Hankook	245 mm	45 mm	18 inch	Summer
Rear Right	5 mm	S	245 mm	45 mm	18 inch	All Season
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Stains & dirt	Hemelbekleding	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small scratch(es)	Acceptable	Yes



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Mirror - Rightside

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Front

Damaged

Rim repair

No



Damage Part
Bumper - Front



Damage Type
Scratch(es)



Repair Type
Spray



Acceptable
No



Damage Part
Mirror - leftside



Damage Type
Broken

Notes
Onderste gedeelte

Repair Type
Replace

Acceptable
No



Damage Part
Frontdoor - Left



Damage Type
Door-edge chipped

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper - Rear



Damage Type
Dent(s) & Scratch(es)



Repair Type
Panelbeating & Spray

Acceptable
No