



RENAULT EXPRESS: 0915-LYN

Vinnumber:	VF1RJK00468838735	Versionname:	Confort 1.5 Blue dCi 55 kW (75 cv) furgón derivado de turismo 55kW 4P manual
First Registrationdate:	14/06/2022	Fiscalpower:	
Expertise Mileage:	150130	Power Kw:	
Bodytype:	Transporter	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	2		
Number head rests	2		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Light Commercial Vehicle		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Radio
Number keys remote	2	
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of climate control	Manual climate control	

Tyres

185/65/15/92 T				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	185/65 R 15 92 T			
Tyre size FR	185/65 R 15 92 T			
Tyre size RL	185/65 R 15 92 T			
Tyre size RR	185/65 R 15 92 T			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	259			
Tyre make RR	259			

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Registration document, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning




Seat cover FL, Tear, Replace



Rear light L, Broken, Replace



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Sliding door R, Scratch(es), Polish



Door FR, Scratch(es), Polish



Wing FR, Scratch(es), Acceptable



Rear panel, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Paint



Tyres, No damage, Check



Bodywork, Glue residues, Remove lettering

