



Volkswagen Tiguan (KKL): 2CCN911

Vinnnumber:	WVGZZZ5NZNW046162	Versionname:	Tiguan Active 1.5TSi 150pk/cv 5p
First Registrationdate:	3/06/2022	Fiscalpower:	
Expertise Mileage:	29143	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/65/17/99 V			
Summer tyres:	Fr.L.	Hankook: 6 mm	Fr.R.	Hankook: 6 mm
	Re.L.	Hankook: 7 mm	Re.R.	Hankook: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				215/65 R 17 99 V
Tyre size FR				215/65 R 17 99 V
Tyre size RL				215/65 R 17 99 V
Tyre size RR				215/65 R 17 99 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bonnet, Scratch(es), Acceptable



Alloy rim RL polished, Scratch(es), Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Acceptable



Kenteken	2CCN911
Merk Model	Volkswagen Tiguan Active 1.5TSi 150pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	6/3/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/3/26	27,200	bougie	Vervangen
6/3/26	27,200	Inspectie met olie vervanging (vast in	Uitvoeren
6/3/26	27,200	klein materiaal	
6/3/26	27,200	luchtfilter interieur	Vervangen
6/3/26	27,200	remvloeistof	Vervangen
6/20/24	15,812	Inspectie met olie vervanging (vast in	Uitvoeren
6/20/24	15,812	klein materiaal	Uitvoeren
6/20/24	15,812	koelwatervloeistof	Vervangen
6/20/24	15,812	luchtfilter interieur	Vervangen
6/20/24	15,812	remvloeistof	Vervangen
6/20/24	15,812	ruitenswisserrubber achter	Vervangen
6/20/24	15,812	ruitenswisserrubber vooraan	Vervangen
6/20/24	15,812	ruitenswisservloeistof	Bijvullen/-laden