



SKODA KAROQ: GL-442-NJ

Vinnumber:	TMBJF7NU8P5035535	Versionname:	SKODA KAROQ 2.0 TDI 116ch DSG7 Style VP [5P] bva 7-116CH-6cv (SUV)
First Registrationdate:	6/01/2023	Fiscalpower:	
Expertise Mileage:	96107	Power Kw:	85
Bodytype:	SUV	Body colour:	White
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Roof bar black	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control	Lining Leather	
		Lining Alcantara	

Tyres

215/50/18/96 W				
Summer tyres:	Fr.L.	Goodyear: 45%	Fr.R.	Goodyear: 55%
	Re.L.	Continental: 35%	Re.R.	Continental: 40%
Tyre profile depth FL				5.1
Tyre profile depth FR				4.7
Tyre profile depth RL				5.9
Tyre profile depth RR				5.7
Tyre size FL				215/50 R 18 96 W
Tyre size FR				215/50 R 18 96 W
Tyre size RL				215/50 R 18 96 W
Tyre size RR				215/50 R 18 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Alloy rim RR bitone/polychrome, Scratch(es), Acceptable



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing FL, Dent(s), Repair and paint (complete)



Door FR, Dent(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Rubber seal for boot lid, Tear, Replace



Internal boot lining R, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Replace



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Historique Maintenance

Immatriculation: GL-442-NJ Date de 1ère immatriculation: 06/01/2023

Modèle: Skoda KAROQ 2.0 TDI 116ch DSG7 Style VP [5P] bva 7-116CH-6cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
01/10/2025	78.561	PRAHA 67	BATTERIE RPLT
	0		REVISION
	0		BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		LIQUIDE DE FREIN
	0		ADBLUE
30/09/2024	50.505	PRAHA 67	PLAQUETTES AV RPLT
	0		PLAQUETTES AR RPLT
	0		REVISION
	0		ADBLUE
21/02/2024	32.916	PRAHA 67	BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
16/11/2023	25.681	NORAUTO SAS (PRODUIT SPE)	REVISION