



PEUGEOT 2008: GF-085-QQ

Vinnumber:	VR3USHNKKJ554113	Versionname:	PEUGEOT 2008 PureTech 100 S&S ALLURE PACK VP [5P] bvm 6-100CH-5cv (SUV)
First Registrationdate:	4/04/2022	Fiscalpower:	
Expertise Mileage:	99654	Power Kw:	75
Bodytype:	SUV	Body colour:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	
Type of climate control	Autom climate control		Lining Other
			Lining Semi-leather

Tyres

	215/60/17/100 V			
Summer tyres:	Fr.L.	Michelin: 70%	Fr.R.	Michelin: 70%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 60%
Tyre profile depth FL				3.7
Tyre profile depth FR				3.6
Tyre profile depth RL				4.8
Tyre profile depth RR				4.2
Tyre size FL				215/60 R 17 100 V
Tyre size FR				215/60 R 17 100 V
Tyre size RL				215/60 R 17 100 V
Tyre size RR				215/60 R 17 100 V
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior, Stain, Cleaning



Floor mat F, Hole, Smart repair



Tyre FR, Out of tolerance, Replace



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing trim FL, Scratch(es), Replace



Door FL, Dent(s), Acceptable



Bumper moulding F, Scratch(es), Replace



Rear bulkhead lining, Scratch(es), Smart repair



Bumper moulding R, Scratch(es), Paint



Historique Maintenance

Immatriculation: GF-085-QQ Date de 1ère immatriculation: 04/04/2022

Modèle: Peugeot 2008 PureTech 100 S&S ALLURE PACK VP [5P] bvm 6-100CH-5cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
21/04/2026	94.355	DEKRA AUTOMOTIVE TRAPPES	CONTROLE TECHNIQUE
24/11/2025	86.591	ESPACE AUTO GENEST'	REVISION ET CLIM ET AIR ET BOUGIES
23/12/2024	66.662	GARAGE DANDIN	COURROIE DISTRIBUTION RPLT
			RECYCLAGE
11/12/2024	66.562	GARAGE DANDIN	REVISION
			FILTRE CLIM RPLT
			BALAI ESSUIE GLACE AR
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
			LAMPE RPLT
29/03/2024	47.264	STELLANTIS &YOU FRANCE SAS	BALAI ESSUIE GLACE AR
			REVISION
			FILTRE CLIM RPLT
			LIQUIDE DE FREIN
			FILTRE A AIR RPLT
			BOITIER D ALLUMAGE RPLT
			BALAIS ESSUIE GLACE AV
			RECYCLAGE
22/05/2023	24.116	STELLANTIS &YOU FRANCE SAS	REVISION
			RECYCLAGE
			BALAIS ESSUIE GLACE AV
			BALAI ESSUIE GLACE AR
			FILTRE CLIM RPLT