



CITROËN C3: FJ-291-MG

Vinnumber:	VF7SXYHYPKT642848	Versionname:	CITROËN C3 BlueHDi 100 S&S BVM Feel Business VP [5P] bvm 5-102CH-5cv (bi-corps)
First Registrationdate:	13/08/2019	Fiscalpower:	
Expertise Mileage:	160139	Power Kw:	75
Bodytype:	Berline	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Steel		
Category:	Passenger Car		

Options

Number of keys total:	2	Radio	
Number keys remote:	1	Central consol F	
GPS big screen color:		Luggage cover	
GPS storage:		Rear parking sensors	
GPS storage:	HD	Seat cover lining	Lining Other
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of climate control:	Autom climate control		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Hankook: 20%	Fr.R.	Hankook: 20%
	Re.L.	Kleber: 35%	Re.R.	Kleber: 40%
Tyre profile depth FL				6.9
Tyre profile depth FR				6.9
Tyre profile depth RL				5.8
Tyre profile depth RR				5.6
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Interior covering B pillar R, Scratch(es), Replace



Interior, Stain, Cleaning



Centre console, Hole, Replace



Armrest F M, Not original part, Acceptable



Interior covering A pillar L, Burned, Smart repair



Centre console, Unclashed, Dismount/Mount



Wing trim FL, Scratch(es), Replace



Outside rear-view mirror housing L, Scratch(es), Acceptable



Roof pillar L, Hail damage, Repair and paint (complete)





Door FL, Scratch(es), Paint



Bonnet, Hail damage, Repair and paint (complete)



Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Bumper spoiler F, Scratch(es), Replace



Roof pillar R, Hail damage, Repair and paint (complete)



Rear spoiler, Hail damage, Repair and paint (complete)



Bumper R, Scratch(es), Paint



Boot lid covering R, Scratch(es), Replace



Roof, Hail damage, Repair and paint (complete)



Historique Maintenance

Immatriculation: FJ-291-MG Date de 1ère immatriculation: 13/08/2019

Modèle: Citroen C3 BlueHDi 100 S&S BVM Feel Business VP [5P] bvm 5-102CH-5cv (bi-corps)

Date	Kilométrage	Fournisseur	Descriptif
30/03/2026	157.347	AMAT AUTOMOBILE	ROULEMENT AVD RPLT
			DIAG
13/01/2026	154.848	AMAT AUTOMOBILE	REVISION ET CLIM
18/09/2025	148.107	AMAT AUTOMOBILE	AMORTISSEURS AV RPLT
			DISQUES PLAQUETTES AV RPLT
07/04/2025	138.503	AMAT AUTOMOBILE	LAMPE CODE AVD RPLT
10/01/2025	130.567	AMAT AUTOMOBILE	LAMPE CODE AVD RPLT
12/12/2024	129.061	AMAT AUTOMOBILE	COURROIE ACCESSOIRES RPLT
			REVISION ET CLIM ET AIR ET CARBURANT
17/04/2024	114.024	AMAT AUTOMOBILE	ESSAI
			INJECTEUR ADBLUE RPLT
			RESERVOIR ADBLUE RPLT
			TELECHARGEMENT CALCULATEUR
			DIAG
27/03/2024	113.603	GARAGE DELMOULY TANGUY	TELECHARGEMENT CALCULATEUR
			DIAG
03/10/2023	103.748	AMAT AUTOMOBILE	ECLAIRAGE DE PLAQUE RPLT
			LIQUIDE DE FREIN
			REVISION ET CLIM
15/09/2023	102.691	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
10/08/2023	101.188	AMAT AUTOMOBILE	ROULEMENT AVD RPLT
09/12/2022	87.149	AMAT AUTOMOBILE	PLAQUETTES AV RPLT
11/10/2022	84.748	GARAGE DELMOULY TANGUY	REVISION
			PLAQUETTES AR RPLT
06/10/2021	60.770	GARAGE DELMOULY TANGUY	REVISION ET CLIM ET AIR ET CARBURANT
			RECYCLAGE
			LIQUIDE DE FREIN
			DIVERS ELEC
07/07/2021	52.868	GARAGE DELMOULY TANGUY	DISQUES PLAQUETTES AV RPLT
10/09/2020	25.362	GARAGE DELMOULY TANGUY	REVISION
			LAMPE CODE AVD RPLT