



VOLVO XC90: 6604-LYR

Vinnumber:	YV1LFH5UDN1872566	Versionname:	2.0 T8 AWD Recharge Inscription Auto todoterreno
First Registrationdate:	20/06/2022	Fiscalpower:	335kW 5P automática
Expertise Mileage:	126959	Power Kw:	
Bodytype:	SUV	Body colour:	Blue
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:			
Fueltype:	Hybrid		
Engine functioning:	Yes		
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of seats:	7		
Number head rests:	7		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Tow bar
Number keys remote	2	Seats electric F L
GPS big screen color		Seats electric F R
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Headlights Xenon/LED/Laser
Steering wheel multifunctional		Headlight sprinkler
Steering wheel leather		Front parking sensors
Seats F heated		Rear parking sensors
Radio multimedia		Roof bar alu
Type of climate control	Autom climate control	Roof rack

Tyres

275/35/22/104 V				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				275/35 R 22 104 V
Tyre size FR				275/35 R 22 104 V
Tyre size RL				275/35 R 22 104 V
Tyre size RR				275/35 R 22 104 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No
Number of charging cables (normal)	2
Number of charging cables (rapid charge)	1

Door panel RL, Scratch(es), Repair/replace (lump sum)



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door RL, Dent(s), Repair and paint (complete)



Fender moulding RL, Scratch(es), Repair and paint (complete)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)




Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FR, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding RR, Missing, Replace



Bumper moulding R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

