



Audi E-TRON 55 BEV 408pk 95kWh Quattro Advanced Edition, Oct-22, 171,413 km



Memo



VIN	WAUZZZGE0PB005763
Initial registration	27-10-2022
Initial Dutch Registration	27-10-2022
European Type Approval	e1*2007/46*1914*17
Mileage reading / hour counter reading	171,413 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2495 kg
Doors	5
Power capacity	300 kW
Emission code / Energy label	Z
Wheelbase	293
Loading space	
Load capacity	
RDW details	
Battery capacity	95 kWh
Range	436 km
Battery health	
Charging cables type	2
AC/DC	ACDC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Black
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Tailgate electrically operated	 Central locking remote control	 Alloy rims
 Adaptive cruise control	 Cruise control	 Metallic paint
 Adaptive power steering	 Electronic Stability Program	 Navigation
 ABS	 Electric windows front	 Parking sensors rear
 Automatic air conditioning ECC	 Electric windows front + rear	 Parking sensors front + rear
 Automatic interior mirror dimmer	 Electric operated seats	 Start immobiliser
 Bluetooth telephone connection	 LED lighting	 Heat reflecting glass

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|-----------------------------|-----------------------------|----------------------------|
| • Adap. damping syst. | • DAB radio | • Lendesteunen (verstelb.) |
| • AEB | • Dakrails | • Lichtmetalen velgen 20" |
| • Alarmsysteem | • Dimlichten aut. | • Luchtvering |
| • Aluminium delen ext. | • EBD | • Multifunctioneel stuur |
| • Armsteun voor | • El.verst.best.stoel+geh. | • Multimedia-voorbereiding |
| • Bagagedek | • Elektr. bed. achterkl. | • Oplaadmogelijkheid |
| • Band.sp.contr.syst. | • ESP | • Parkeersensor voor |
| • BAS | • Forward Collision Warning | • Passagiersairbag |
| • Bestuurdersairbag | • Hoofd airbag(s) a. | • Schakelen op stuur |
| • Bluetooth telefoonvoorb. | • Hoofd airbag(s) v. | • Spraakbediening |
| • Bots herkenning+activatie | • In delen neerkl. achterb. | • Var. stuuroverbrenging |
| • Buitensp. elekt. inklapb. | • Interieur voorverwarming | • Verstelbaar stuur |
| • Buitensp. elektr. + geh. | • LED achterlichten | • Voll. dig. instr. paneel |
| • Buitensp. elektr. + verw. | • LED dagrijverlichting | • WiFi voorbereiding |
| • Connected services | • LED koplampen | • Zij airbag(s) v. |
| • Cruise control | • Lederen stuurwiel | |



Comments

No remarks

Vehicle state

MOT due date	27-10-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location	Wheel locks	Not present
			Owner		




Tyres

Rim size	20"		
Wheel	Brand	Type	Tread depth
Front wheel left	Continental	Summer tyre	3 mm
Front wheel right	Continental	Summer tyre	3 mm
Rear wheel left	Continental	Summer tyre	5 mm
Rear wheel right	Continental	Summer tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
Unacceptable damage		
1	Interior	smoke odor
2	Floor covering	burn hole(s)
3	Head liner	dirt (interior)
4	Wielkuip bekleding a l	scratch(es)
5	Front door left	scratch(es)
6	Rear door left	scratch(es)
7	Front wing left	scratch(es)
8	Engine bonnet	stone impact
9	Front wing right	distorted, gebogen

10		Deur v r sierlijst	various damage (see photo)
11		Wielkuip bekleding v r	various damage (see photo)
12		Deur a r sierlijst	scratch(es)
13		Rear door right	dent(s)
14		Wielkuip bekleding a r	scratch(es)
15		Rear right rim	scratch(es)
16		Charging cable for charging station	Missing part, zat vast in laadpaal, gemeld
17		Rear bumper	scratch(es)
18		Rear bumper	scratch(es)

Comments

No remarks

Vendor