



**Citroen C5: P756SP**

Vinnumber:	<b>VR7ARHNSKNL017707</b>	Versionname:	<b>C5 Aircross 1.2 PureTech 96kW S&amp;S Feel</b>
First Registrationdate:	<b>31/05/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>52071</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Polar White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Parking lot:	<b>356</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Lining semi-leather
Autom climate control		Rear parking sensors
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 55 / 18 / 102 / H / Aluminium	4,2 mm	Goodyear	All season
	Right	225 / 55 / 18 / 102 / H / Aluminium	3,3 mm	Goodyear	All season
Rear	Left	225 / 55 / 18 / 102 / H / Aluminium	5,7 mm	Goodyear	All season
	Right	225 / 55 / 18 / 102 / H / Aluminium	5,3 mm	Goodyear	All season

**Assistance equipment**

Number of charging cables (rapid charge)	<b>0</b>
<b>Service, Maintenance, Execute</b>	



**Bonnet, Chemical polution, Polish**



**Door RR, Dent(s), Paintless dent repair**



**Door FR, Dent(s), Repair and paint (complete)**



Roof, Dent(s), Paintless dent repair



<b>Kenteken</b>	P756SP
<b>Merk Model</b>	Citroen C5 Aircross 1.2 PureTech 96kW S&S Feel
<b>Brandstofsoort</b>	Benzine
<b>Datum deel1</b>	31-05-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
19-05-26	51.290	APK
03-06-25	38.967	Bougie
03-06-25	38.967	Luchtfilter
03-06-25	38.967	Onderhoudsbeurt
03-06-25	38.967	Remblokken voorzijde
13-12-24	34.531	Vervanging band
18-06-24	26.896	Onderhoudsbeurt
18-06-24	26.896	Remvloeistof
05-12-23	20.885	Vervanging band
03-07-23	13.656	Onderhoudsbeurt
05-08-22	4	Vervanging band