DEKRA

DEKRA Automotive Solutions

Condition Report

Vehicle details

VIN	WF0PXXGCH PRK23015	Mileage	75 761 km	Engine (Fuel) Type	Petrol
Licence Plate	2FNS058	Registration date	26/06/2024	Engine size	999
Brand	FORD	Fuel level	-	Transmission	Manual
Model	FocusBreak-CGE-2018	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	13/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique
















Other technical information

Spare wheel kit	✔
Load cover	✔

Tyres

Goodyear 215/60/17 V All seasons 3.0 mm

Goodyear 215/60/17 V All seasons 3.0 mm



Goodyear 215/60/17 V All seasons 5.0 mm

Goodyear 215/60/17 V All seasons 5.0 mm

Damages

1



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	29.62€

2



Part	Exterior door mirror shell
Position	Left
Damages	Chemical deposit
Severity	-
Repair mode	Polishing
Net cost (Excluding VAT)	17.77€

DEKRA

DEKRA Automotive Solutions

Condition Report

3



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

4



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	339.25€

5



Part	Bumper
Position	Back
Damages	Dent & Chips
Severity	-
Repair mode	Repair
Net cost (Excluding VAT)	398.50€

6



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	165.00€

7



Part	Door
Position	Front right
Damages	Stone impact
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

Summary Inspection

Net Price (Exclusing VAT)	950.14€