



Volkswagen Passat:

Vinnumber:	WVWZZZ3CZME121228	Versionname:	
First Registrationdate:	1/07/2021	Fiscalpower:	
Expertise Mileage:	130207	Power Kw:	110
Bodytype:		Body colour:	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1522
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	Tow bar collapsible
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection


Tyres

225/45/17/91 W				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				225/45 R 17 91 W
Tyre size FR				225/45 R 17 91 W
Tyre size RL				225/45 R 17 91 W
Tyre size RR				225/45 R 17 91 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	1224,41
Bonnet, Chemical pollution, Acceptable:	0,00



Windscreen, Bad repair, Check 0,00



Wing FL, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete) 161,81



Bumper R, Scratch(es), Acceptable 0,00



Rear window, Scratch(es), Replace 482,69



Door RR, Scratch(es), Spot repair 148,33



Wing RR, Scratch(es), Repair and paint (complete) 431,58

