

2-FDW-163

2-FDW-163 · MY23 Mild-Hybrid 158 XTronic 2WD Business Premium · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FDW-163	Fuel Type	Hybrid Gasoline
Manufacturer	NISSAN	VIN	SJNTAAJ12U1374134
Model	Qashqai	Cylinder Capacity	1.332 ^{cm3}
Model Versions	MY23 Mild-Hybrid 158 XTronic 2WD Business Premium	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	05-04-2024
Body Type	5 door hatchback	Odometer	90.307 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	116		

Images





Accessories

ABS	Electrically adjustable driver's seat
Airbags	
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Panorama roof
Centre armrest	Rear view camera
Cruise control	Seat heating
Electric rear windows	Steering wheel multifunction
Electric windows front	Steeringwheel - Heated
	Windscreen - Heated

Condition

Condition exterior	Adequate	Maintenance Remarks	Onderhoud uitvoeren
Condition interior	Adequate	Last maintenance odometer	59.850
Last Maintenance	22-10-2025	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Imperial	235 ^{mm}	55 ^{mm}	18 ^{inch}	All Season
Rear Left	5 ^{mm}	Imperial	235 ^{mm}	55 ^{mm}	18 ^{inch}	All Season
Front Right	4 ^{mm}	Imperial	235 ^{mm}	55 ^{mm}	18 ^{inch}	All Season
Rear Right	5 ^{mm}	Imperial	235 ^{mm}	55 ^{mm}	18 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Right

Small scratch(es)

Touch-up / Polish

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

small dents / small scratches

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Small scratch(es)

Acceptable

Yes



Damage Part
Bumper – Front

Damage Type
Stonechipping

Repair Type
Touch-up / Polish

Acceptable
No



Damage Part
Frontdoor – Left

Damage Type
Door-edge chipped

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Fender – Rear Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Missing	Trekoogkapje	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No