



Expertise

Protocol number: 46721848  
Order No. / Reference: 26740816  
Inspection date: 13 Jul 2026

Manufacturer: Volkswagen

Model: ID.4 Performance Upgrade Pro

VIN: WVGZZZE2ZPE049851



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen ID.4 Performance Upgrade Pro

|                                      |                   |
|--------------------------------------|-------------------|
| Vehicle Identification number        | WVGZZZE2ZPE049851 |
| Mileage (Read)                       | 112,982 km        |
| First registration                   | 18 Apr 2023       |
| Number of holders                    | 1                 |
| Next periodical technical inspection | 04/2026           |
| (Report not on hand)                 |                   |

|                           |                     |
|---------------------------|---------------------|
| Fuel type                 | Electric            |
| Power                     | 70 kW               |
| Gearbox / Number of gears | Direct drive / 1    |
| Type of drive             | Rear drive          |
| Type of vehicle           | Station wagon       |
| Colour / colour code      | Mythos Black (Y9T)  |
| Doors / Seats             | 5 / 5               |
| Upholstery type           | Alcantara / Leather |
| Colour of upholstery      | Black               |

|                    |            |
|--------------------|------------|
| Re-import          | no         |
| readiness to drive | Roadworthy |



## Vehicle details

|                                                  |                          |                                |                                                            |
|--------------------------------------------------|--------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | digital proof / complete | <b>Next maintenance in</b>     | 284 Tag(e)                                                 |
| <b>Last service on / at</b>                      | 04/2025 at 79,113 km     |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                    | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                          | <b>Letter No.</b>              | GS506148                                                   |
| <b>Previous damage / Accident</b>                | None detectable          | <b>Repainting</b>              | None detectable                                            |
| <b>Inspection conditions</b>                     | sufficient               | <b>Lifting equipment / pit</b> | No                                                         |
| <b>Test drive</b>                                | Not performed            | <b>Engine function test</b>    | Performed                                                  |
| <b>readiness to drive</b>                        | Roadworthy               |                                |                                                            |
| <b>Manufacturer key number/ type code number</b> | 0603 / CLQ 00114         |                                |                                                            |
| <b>Emission standard</b>                         | 2017/1151                | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 2,660 kg                 | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size       | Type of tyre                | Manufacturer | Tread depth |
|----|-----------------|-----------------------------|--------------|-------------|
| 1) | 235/55 R19 101T | Summer tyres on Light alloy | Pirelli      | 5mm / 5mm   |
| 2) | 255/50 R19 103T | Summer tyres on Light alloy | Pirelli      | 4mm / 4mm   |

### Replacement

| Typ | Tyre size | Type of tyre            | Manufacturer | Tread depth |
|-----|-----------|-------------------------|--------------|-------------|
|     | Tirefit   | Expiration date 02/2027 |              |             |

**Legend:** Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



## Equipment

### Standard equipment

- 2 USB-C ports on the front (charging power up to 45 W)
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Ambient lighting, 10 colors
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- Car2X
- e-Sound (artificially generated engine noise to inform other road users about the approach of the e-vehicle)
- Parking aid (warning signals for obstacles in the front and rear area)
- Driving profile selection
- Back window, heater
- Infotainment accessories: Online update capability from ID.Software 2.1
- "Climatronic" air conditioning system (active combination filter - stationary air conditioning)
- Front and rear headrests (5)
- Charging: 11 kW AC charging power (alternating current)
- LED headlights with automatic headlight control
- Steering wheel: Multifunction steering wheel with touch controls
- Fatigue detection
- Emergency call service (no registration required, service is activated upon delivery)
- Upholstery: Seat center panels of the front seats and the outer rear seats in "Matrix" fabric
- Radio accessories: Digital radio reception DAB+
- Wheels: Steel wheels (4) 8 J x 19 (tires 235/55 R 19 front, tires 255/50 R 19 rear - wheel covers)
- Keyless Start system (without safe locking)
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear - warning tone and light for unfastened seat belts at the front and rear)
- Voice control
- Lane keeping assistant "Lane Assist"
- Telephone interface
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: "Discover Pro" navigation function
- Central locking including remote control
- Turning brake function and evasive steering support
- Airbags: Front and rear head airbags, front side airbags, center airbag
- App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- black roof rails
- Black surround for the infotainment display and central controls
- ESP Electronic Stability Program (incl. ABS Anti-lock Braking System)
- Transmission: 1-speed automatic
- rear window wiper
- Interior mirror automatically dimming
- ISOFIX mounting points for child seats (mounting points for child seats on the outer rear seats and on the front passenger seat, i-Size compatible)
- Mode 3 Type 2 charging cable, 16 A
- Charging: Maximum DC charging power depends on the traction battery.
- Makeup mirrors in the sun visors
- Centre console
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Stainless steel pedals in a "Play/Pause" design
- Radio "Ready 2 Discover"
- Radio accessories: 6 + 1 speakers
- Tire pressure monitoring system
- LED taillights
- Windscreen wiper intermittent control
- Electromechanical power steering (speed-dependent control)
- Seats: Armrest for front seats
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat undivided, backrest asymmetrically split and foldable
- Bumpers in body color
- Ambient lighting with logo projection
- Traffic sign recognition
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear

### Extra equipment

- foldable tow bar
- Paint finish: Metallic
- Package: Design Package "Plus"
- Interior Style "Plus" Platinum Gray
- Package: Assistance Package "Plus" IQ.DiVmT
- Wheels: LM Hamar 8Jx19 Black / gloss



## Brief expert findings

|                      |                                                                                                                                                                                                                                               |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)                                                                  |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.                                                                     |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                                                                                         |
| Engine function test | An engine test run was performed.                                                                                                                                                                                                             |
| readiness to drive   | The vehicle was roadworthy at the time of inspection.                                                                                                                                                                                         |

## Value reducing factors

| No. | Component group         | Description                                                        |
|-----|-------------------------|--------------------------------------------------------------------|
| 1   | Bonnet                  | Bonnet - dent(s) - Smooth repair work                              |
| 2   | Misc.                   | Main inspection - Due - Perform                                    |
| 3   | Door - front right side | Brightware - lower - Scratch(es) - Replace                         |
| 4   | Mudguard - right side   | Wheel well extension - Scratch(es) - Replace                       |
| 5   | Equipment               | Vehicle key - Damaged - Replace                                    |
| 6   | Front bumper            | Spoiler - Scratched - Replace                                      |
| 7   | Mudguard - left side    | Mudguard - left side - Dent / paintcoat damage - Repair and paint  |
| 8   | Mudguard - right side   | Mudguard - right side - Dent / paintcoat damage - Repair and paint |
| 9   | Door - front left side  | Door - Scratch(es) - Paint                                         |
| 10  | Door - front right side | Door - Deformed - Repair and paint                                 |
| 11  | Boot lid / rear door    | Boot lid - Deformed - Repair and paint                             |

## Wear and tear

| No. | Component group        | Description                       |
|-----|------------------------|-----------------------------------|
| 1   | Door - rear right side | Door - dent(s) - No deduction     |
| 2   | Door - rear left side  | Door - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



**Figure 1:** Diagonal front (left)



**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.





Figure 22: Misc.



Figure 23: Misc.



Damage 1: Bonnet: Bonnet - dent(s) - Smooth repair work



**Damage 1:** Bonnet: Bonnet - dent(s) - Smooth repair work



**Damage 1:** Bonnet: Bonnet - dent(s) - Smooth repair work



**Damage 1:** Bonnet: Bonnet - dent(s) - Smooth repair work



**Damage 3:** Door - front right side: Brightware - lower - Scratch(es) - Replace



**Damage 3:** Door - front right side: Brightware - lower - Scratch(es) - Replace



**Damage 4:** Mudguard - right side: Wheel well extension - Scratch(es) - Replace



**Damage 4:** Mudguard - right side: Wheel well extension - Scratch(es) - Replace



**Damage 5:** Equipment: Vehicle key - Damaged - Replace




**Damage 6:** Front bumper: Spoiler - Scratched - Replace




**Damage 6:** Front bumper: Spoiler - Scratched - Replace



**Damage 7:** Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



**Damage 7:** Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



**Damage 7:** Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint




**Damage 8:** Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



**Damage 8:** Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




**Damage 8:** Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



**Damage 8:** Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



**Damage 9:** Door - front left side: Door - Scratch(es) - Paint




**Damage 9:** Door - front left side: Door - Scratch(es) - Paint



**Damage 9:** Door - front left side: Door - Scratch(es) - Paint



**Damage 10:** Door - front right side: Door - Deformed - Repair and paint




**Damage 10:** Door - front right side: Door - Deformed - Repair and paint




**Damage 10:** Door - front right side: Door - Deformed - Repair and paint



**Damage 11:** Boot lid / rear door: Boot lid - Deformed - Repair and paint



**Damage 11:** Boot lid / rear door: Boot lid - Deformed - Repair and paint



**Damage 11:** Boot lid / rear door: Boot lid - Deformed - Repair and paint



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZE2ZPE049851

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN ID.4 Performance Upgrade Pro

| Datum      | KM-Stand | Beschreibung                                                                      |
|------------|----------|-----------------------------------------------------------------------------------|
| 13.10.2025 | 92.176   | Systemtest/Eigendiagnose                                                          |
| 30.04.2025 | 79.113   | Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst; Wartung<br>Sonstiges |