



FORD Kuga: 3382-MFW

| | | | |
|------------------------------------|--------------------------|-------------------------|---|
| Vinnumber: | WF0FXXWPMHNG15615 | Versionname: | ST-Line X 2.5 Duratec FHEV 140kW 4x4 Aut todoterreno 140kW 5P automática |
| First Registrationdate: | 29/03/2023 | Fiscalpower: | |
| Expertise Mileage: | 241985 | Power Kw: | |
| Bodytype: | SUV | Body colour: | White |
| Gearbox: | Automatic | Type of rims (mounted): | Aluminium |
| Transmission: | | | |
| Fueltype: | Hybrid | | |
| Engine functioning: | Yes | | |
| Battery functioning: | Yes | | |
| Vehicle running: | Yes | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Certificate of Conformity: | Yes | | |
| Category: | Passenger Car | | |
| Registration Certificate Car (BE): | No | | |

Options

| | | |
|------------------------------|------------------------------|-----------------------|
| Number of keys total | 2 | Seats electric F L |
| Number keys remote | 2 | Central consol F |
| GPS big screen color | | Luggage cover |
| Windows electric F | | Front parking sensors |
| Windows electric R | | Rear parking sensors |
| Cruise Control | | Roof bar black |
| Steering wheel multifunction | | |
| Steering wheel leather | | |
| Radio multimedia | | |
| Type of climate control | Autom climate control | |


Tyres

| | | | | |
|------------------------|-------|-----------------------|-------|--------------------------|
| 245/45/20/103 W | | | | |
| Summer tyres: | Fr.L. | Goodyear: 4 mm | Fr.R. | Goodyear: 4 mm |
| | Re.L. | Goodyear: 5 mm | Re.R. | Goodyear: 5 mm |
| Tyre profile depth FL | | | | 4.0 |
| Tyre profile depth FR | | | | 4.0 |
| Tyre profile depth RL | | | | 5.0 |
| Tyre profile depth RR | | | | 5.0 |
| Tyre size FL | | | | 245/45 R 20 103 W |
| Tyre size FR | | | | 245/45 R 20 103 W |
| Tyre size RL | | | | 245/45 R 20 103 W |
| Tyre size RR | | | | 245/45 R 20 103 W |
| Tyre make FL | | | | 259 |
| Tyre make FR | | | | 259 |
| Tyre make RL | | | | 259 |
| Tyre make RR | | | | 259 |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

Boot lid covering R, Scratch(es), Replace



Interior, Dirty, Cleaning



User's manual, Missing, Repair/replace (lump sum)



Service book, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Repair/replace (lump sum)



Windscreen, Stone chip(s), Replace



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Wing FR, Scratch(es), Repair and paint (complete)



Wing trim FR, Scratch(es), Paint



Tyre FR, Tear, Acceptable



Door FR, Dent(s) and scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)



Outer door handle RR, Scratch(es), Paint



Wing RR, Scratch(es), Repair and paint (complete)



Bumper moulding R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Bodywork, Glue residues, Acceptable



