







· 1.0 TSI 110pk R-Line · 4 June 2026 · Schiphol

Specifications

License Plate Number		VIN	WVGZZZC1ZMY076581
Manufacturer	VOLKSWAGEN	Cylinder Capacity	999 ^{cm³}
Model	T-Cross	Transmission Type	Handmatig geschakelde transmissie6
Model Versions	1.0 TSI 110pk R-Line	MOT	26-08-2027
Body Type	5 door hatchback	First Admission	20-08-2021
Color	Blue	First Registration	20-08-2021
Paint Type	Metallic	Odometer	210.723 ^{Km}
		Numer Of Keys	2
Production Year	2021	Interior	Black
KW	81	Number Headrests	5
Fuel Type	Gasoline		

Images





Accessories

ABS

Airbags

Alloy wheels

ASR

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable & heated exterior mirrors

Leather steering wheel

Navigation system

Parking sensors

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Vredestein	225 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Left	6 ^{mm}	Vredestein	225 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Front Right	6 ^{mm}	Vredestein	225 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Right	6 ^{mm}	Vredestein	225 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Spare Tire Type	Fully Fledged					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Dashboard

Scratch(es)

Plastic Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Left

Door-edge chipped

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Small scratch(es)

Acceptable

Yes



Damage Part
Bumper - Front

Damage Type
Scratch(es)

Notes
rechts

Repair Type Acceptable
Panelbeating No
& Spotrepair





Damage Part
Overfender

Damage Type
Small scratch(es)

Notes
RV

Repair Type Acceptable
Acceptable Yes



Damage Part
Alloys


Damage Type
Damaged

Notes
LV - LA - RV

Repair Type Acceptable
Rim repair No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Small scratch(es)	Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Small scratch(es)	Acceptable	Yes





Damage Part
spoiler RB

Damage Type
Scratch(es)

Repair Type
Plastic Repair

Acceptable



Damage Part
Skirt - Left

Damage Type
Small dent(s)

Repair Type
Panelbeating &
Spotrepair

Acceptable

No




Damage Part
Interior

Damage Type
Stains & dirt

Repair Type
Cleaning

Acceptable

No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Worn	vloer LV	Cloth Repair	No