



VOLKSWAGEN TOURAN: [REDACTED]				
Vinnumber:	WVGZZZ1TZMW017748	Versionname:	2.0 TDi 90kW Highline	
First Registrationdate:	25/01/2021	Fiscalpower:		
Expertise Mileage:	81350	Power Kw:	90	
Bodytype:		Body colour	Blue	
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	2431	
Fueltype:	Diesel			
Maintenance	OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Registration Certificate Home (BE)	No			
Options				
Number of keys total	2	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Radio multimedia		Type of Tow bar	Tow bar collapsible	
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-Alcantara			
Type of climate control	Autom climate control			
Type of GPS storage	HD			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/60/16/96 W			
	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/60 R 16 96 W
Tyre size FR				205/60 R 16 96 W
Tyre size RL				205/60 R 16 96 W
Tyre size RR				205/60 R 16 96 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265
Assistance equipment				
Repair kit	Yes	Compressor		Yes
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT				479,76
Air vent RM, Broken, Replace				168,65



Bumper F, Repaired, Acceptable 0,00



Windscreen, Repaired, Acceptable 0,00



Door FL, Scratch(es), Acceptable 0,00



Wiper arm rear, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Bumper R, 0,00



lid covering R, Scratch(es), Acceptable 0,00



Wheel aperture RL, Dent(s) and scratch(es), Spot repair 178,08



Door FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Dent(s) and scratch(es), Acceptable	0,00
--	------



Step R, Dent(s) and scratch(es), Acceptable	0,00
---	------



Wing RR, Scratch(es), Acceptable	0,00
----------------------------------	------



Alloy rim FR, Scratch(es), Repair and paint (complete)	133,03
--	--------

