



Volvo XC40: R738KB

Vinnumber:	YV1XZEFV2P2945433	Versionname:	XC40 Recharge 170kW/ 70kWh Plus automaat
First Registrationdate:	29/09/2022	Fiscalpower:	
Expertise Mileage:	161060	Power Kw:	170
Bodytype:		Body colour	Black Stone solid
Gearbox:	Automatic	Paint type	Opaque
Transmission:		Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	848
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	No		

Options

Number of keys total	2	Rear parking sensors
GPS		Hook
Autom climate control		Rear view camera
Radio multimedia		

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	255 / 45 / 19 / 104 / Y / Aluminium	7,0 mm	Bridgestone	All season
	Right	255 / 45 / 19 / 104 / Y / Aluminium	7,3 mm	Bridgestone	All season
Rear	Left	255 / 45 / 19 / 104 / Y / Aluminium	5,2 mm	Bridgestone	All season
	Right	255 / 45 / 19 / 104 / Y / Aluminium	5,2 mm	Bridgestone	All season

Assistance equipment

Number of charging cables (rapid charge)	1
--	----------


Interior, Stain, Cleaning



Wing FL, Scratch(es), Repair and paint (complete)



Wheel arch cover FL, Scratch(es), Replace



Bumper F, Scratch(es), Repair and paint (partial)



Bonnet, Scratch(es), Repair and paint (complete)



Door RR, Dent(s), Paintless dent repair



Bumper corner RR, Scratch(es), Repair and paint (complete)



Shutter / cover R, Missing, Replace



Bumper corner RL, Scratch(es), Repair and paint (complete)



Kenteken	R738KB
Merk Model	Volvo XC40 Recharge 175kW/ 69kWh Plus automaat
Brandstofsoort	Elektrisch
Datum deel1	29-09-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
21-07-26	160.884	APK
21-07-26	160.884	Onderhoudsbeurt
21-07-26	160.884	Remvloeistof
21-07-26	160.884	Ruitenwischerblad(en) voorzijde
21-07-26	160.884	Vervanging band
30-09-25	128.632	Onderhoudsbeurt
07-01-25	93.190	Vervanging band
14-03-24	61.399	Onderhoudsbeurt
14-03-24	61.399	Vervanging band
04-08-23	31.538	Onderhoudsbeurt
23-10-22	0	Accu