

2-FBA-722

2-FBA-722 · ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 -Clipper · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FBA-722	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPRB65585
Model	Focus SW	Cylinder Capacity	999 ^{cm3}
Model Versions	ST Line X 1.0i EcoBoost 155pk - 114kW - Mhev A7 - Clipper	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	12-03-2024
Body Type	5 door hatchback	Odometer	89.807 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Black
Production Year	2024	Number Headrests	5
KW	114		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel – Heated

Windscreen – Heated

Condition

Condition exterior

Adequate

Maintenance Remarks

Motorolie verversen

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Milestone	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	5 ^{mm}	Milestone	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	4 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	small dents / small scratches	Restyle / Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Small dent(s)	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Front Left	Dislocated / Loose	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Small dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Scratch(es)	Spray	No



Damage Part

Bumper - Rear

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No