

INSPECTION REPORT

End of contract

GENERAL INFO

File	315740
License plate	1YSZ620
Vehicle identification number	VF3VFAHKKLZ079022
Dossier	2020309078
Make	Peugeot Exp.Ut.2.0D 120 L3 Pre
Mileage	55024
First registration	03/12/2020
client availability date	22/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
17	Bumper Front // Replace without painting	Y
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
87	Door Front Left / Trim / Replace	Y
102	Door Rear Left // Smart Repair Large	N
137	Bumper Rear // Replace without painting	N
197	Door Rear Right / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
233	Wing Front right // Painting	Y
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
593	Trunk Lid Interior Coating / MDF Rear Right / Replace	N

Damage Pictures



Door Front Left / Trim / Replace-scratch



Wing Front Left // Painting-scratch



Bumper Front // Replace without painting-scratch




Wing Front right // Painting-scratch



Door Rear Left // Smart Repair Large-dent



Rocker Panel Right // Smart Repair Medium-dent



Door Front Right // Repair & Painting-scratch + dent



Bumper Rear // Replace without painting-scratch + dent



Trunk Compartment / Side Cover Left / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked



Trunk Lid Interior Coating / MDF Rear Right / Replace-cracked



Windshield // Repair-glass damage




Trunk Compartment / Side Cover Right / Replace-missing



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch