



BMW SERIE 1

Immatriculation	-
VIN	WBA7K310707M40035
Kilométrage	38 180 km
Première immatriculation	28/04/2023
Couleur carrosserie	Noir

DÉTAILS DE L'INSPECTION

Adresse d'inspection	Date de l'inspection	09/06/2026 13:41:57
Adresse d'inspection		

INFORMATIONS SUR LE VÉHICULE

Marque	BMW	Type de carrosserie	Berline
Modèle	SERIE 1	Nbre portes	5
VIN	WBA7K310707M40035	Nbre sièges	5
Première immatriculation	28/04/2023	Transmission	Avant
Kilométrage	38 180 km	Couleur intérieur	Noir
Catégorie	Vehicule particulier	Couleur carrosserie	Noir

DOCUMENTS ET CLÉS

Nbre clés total	1	Certificat immatriculation (original)	Non
Nbre clés télécommandes	1	Certificat immatriculation (original)	N/A

OPTIONS


Batterie fonctionnante	Oui	Stockage GPS	HD
Moteur fonctionnant	Oui	Camera de recul	Oui
Véhicule roulant	Oui	Cache bagages	Oui
Niveau carburant	75	Cric	Oui
GPS	Oui	Nature de peinture	Metallisé

PNEUS

Pneus montés

Emplacement	Position	Profondeur des sculptures	Fabricant	Dimensions	Type de pneu	Type de jantes	Runflat
Avant	Gauche	4,5 mm	Bridgestone	225/40 R 18 92 Y	Eté	Aluminium	Non
Avant	Droite	4,6 mm	Bridgestone	225/40 R 18 92 Y	Eté	Aluminium	Non
Arrière	Gauche	5,5 mm	Bridgestone	225/40 R 18 92 Y	Eté	Aluminium	Non
Arrière	Droite	5,4 mm	Bridgestone	225/40 R 18 92 Y	Eté	Aluminium	Non

DAMAGES



Bumper R

Damage type	Deformed / Strained
Repair mode	Replace and paint



Bumper FR

Damage type	Scratch(es)
Repair mode	Paint



Remote ignition key (no insert)

Damage type	Missing
Repair mode	Forfeit



Floor mat F

Damage type	Hole
Repair mode	Smart repair



Alloy rim FR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)





Alloy rim FL bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



Alloy rim RR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)




Alloy rim RR bitone/polychrome

Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)



Rear light R

Damage type	Broken
Repair mode	Replace



Bumper grille

Damage type	Broken
Repair mode	Replace



Interior

Damage type	Dirty
Repair mode	Cleaning



Shutter / cover F

Damage type	Unclashed
Repair mode	Dismount/Mount

COMMERCIAL PHOTOS

