


2-DCN-031

2-DCN-031 · Break Move! 1.0 eTSI 110CV (81kW) DSG 7v Mild Hybrid EURO 6 AP · 16 April 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DCN-031	Fuel Type	Hybrid Gasoline
Manufacturer	SEAT	VIN	VSSZZZKL6PR027829
Model	Leon	Cylinder Capacity	999 ^{cm³}
Model Versions	Break Move! 1.0 eTSI 110CV (81kW) DSG 7v Mild Hybrid EURO 6 AP	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	02-02-2023
Color	Silver	Odometer	108.782 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	81	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Condition

Condition exterior Adequate Maintenance Remarks Bandenspanning controleren

Condition interior Adequate Previous Repairs Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Nexen	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Rear Left	6 ^{mm}	Nexen	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Front Right	2 ^{mm}	Nexen	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Rear Right	6 ^{mm}	Nexen	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Spare Tire Type		None				

Damages



Damage Part

Fender - Rear Left



Damage Type

Small dent(s)

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Reardoor - Left



Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Alloy - Left Front



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part
Windscreen - Front



Damage Type
Chipped

Repair Type
Window Repair

Acceptable
No



Damage Part
Hood



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
spoiler FB



Damage Type
Scratch(es)

Repair Type
Spotrepair

Acceptable
No



Damage Part
Bumper - Front



Damage Type
Scratch(es)

Repair Type
Spotrepair

Acceptable
No



Damage Part
Alloy - Right Front



Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Frontdoor - Right



Damage Type
Small scratch(es)

Repair Type
Polish

Acceptable
No



Damage Part
Bumper - Rear



Damage Type
Scratch(es)



Repair Type
Spray

Acceptable
No



Damage Part
Roof



Damage Type
Scratch(es)



Repair Type
Spray

Acceptable
No



Damage Part
Skirt - Left



Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part

Interior



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No