

2-DRE-543

2-DRE-543 · ST-line 125pk 92kw mHEV M6 Clipper · 21 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DRE-543	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0PXXGCHPPL85203
Model	Focus	Cylinder Capacity	999 ^{cm3}
Model Versions	ST-line 125pk 92kw mHEV M6 Clipper	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	02-06-2023
Color	Silver	Odometer	87.847 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	92	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Roller cover / parcel shelf
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel - Heated
Electric rear windows	Windscreen - Heated

Condition

Condition exterior Adequate	Last Maintenance Unknown
Condition interior Adequate	Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Landsail	215 mm	50 mm	17 inch	All Season
Rear Left	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Front Right	5 mm	Landsail	215 mm	50 mm	17 inch	All Season
Rear Right	4 mm	Goodyear	215 mm	50 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender – Rear Left	Damaged	Raamrubber	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Left	Damaged	Slot	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Scratch(es)

Spray

No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small dent(s)	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Windscreen – Rear	Missing	Ruitenwisser	Replace	No



Damage Part

Damage Type

Repair Type

Acceptable

Interior

Stains & dirt

Cleaning

No