



**PEUGEOT 508**

Vinnumber:	<b>VR3FBYHZRLY024573</b>	Versionname:	<b>1.5 BlueHDi 130 S&amp;S EAT8 GT Line</b>
First Registrationdate:	<b>10/07/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>112908</b>	Power Kw:	<b>96</b>
Bodytype:		Body colour:	<b>Red</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>3113</b>
Fueltype:	<b>Diesel</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Number of keys total	<b>2</b>	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Sun Roof electric	
Seats F heated		Panoramic roof	
Radio multimedia		Luggage cover	
Type of headlighting	<b>Headlighting LED</b>	Front parking sensors	
Type of GPS	<b>GPS big screen color</b>	Rear parking sensors	
Type of Lining	<b>Lining artificial leather</b>	Type of Tow bar	<b>No Tow bar</b>
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

**Tyres**

235/45/18/92 H				
Summer tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>235/45 R 18 92 H</b>
Tyre size FR				<b>235/45 R 18 92 H</b>
Tyre size RL				<b>235/45 R 18 92 H</b>
Tyre size RR				<b>235/45 R 18 92 H</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>265</b>
Tyre make FR				<b>265</b>
Tyre make RL				<b>261</b>
Tyre make RR				<b>261</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>1504,21</b>
Seat cover FL, Damaged, Acceptable	<b>0,00</b>



Door RL, Dent(s), Acceptable 0,00



Door FL, Scratch(es), Repair and paint (complete) 445,79



Wing FL, Scratch(es), Acceptable 0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete) 204,21



Bumper R, Scratch(es), Acceptable 0,00




Alloy rim FR polished, Scratch(es), Repair and paint (complete) 204,21



Door FR, Scratch(es), Repair and paint (complete) 445,79



Door RR, Scratch(es), Acceptable 0,00



Alloy rim RR polished, Scratch(es), Repair and paint (complete) 204,21

