MACADAM








PEUGEOT 2008: 4526-MWS

Vinnumber:	**VR3USHNK7RJ893486**	Versionname:	**Allure Puretech 100 S&S 6 Vel. MAN todoterreno 75kW 5P manual**
First Registrationdate:	**28/11/2024**	Fiscalpower:	
Expertise Mileage:	**6522**	Power Kw:	
Bodytype:	**SUV**	Body colour	**Grey**
Gearbox:	**MAN 6 VIT**	Type of rims (mounted)	**Aluminium**
Transmission:			
Fueltype:	**Petrol**		
Engine functioning	**Yes**		
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Central consol F	
Number keys remote	**1**	Luggage cover	
GPS big screen color		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Roof bar black	
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Radio multimedia			
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**215/60/17/96 H**			
	Fr.L.	**Goodyear: 4 mm**	Fr.R.	**Goodyear: 4 mm**
	Re.L.	**Goodyear: 4 mm**	Re.R.	**Goodyear: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**4.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/60 R 17 96 H**
Tyre size FR	**215/60 R 17 96 H**
Tyre size RL	**215/60 R 17 96 H**
Tyre size RR	**215/60 R 17 96 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Door panel RR, Scratch(es), Repair/replace (lump sum)




Malfunction indicator, Blinking, Check




Door FL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)




Fender moulding RL, Scratch(es), Repair and paint (complete)




Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)




Bumper spoiler Rear, Dent(s) and scratch(es), Repair and paint (complete)




Tyres, No damage, Check











ALPHABET

Datos del vehículo

Marca	PEUGEOT	Matrícula	4526-MWS
Modelo	2008	VIN	VR3USHNK7RJ893486
Versión	Allure Puretech 100 S&S 6 Vel. MAN todoterreno 75kW 5P manual		

Histórico

Fecha	Descripción	Kilómetros	Taller
11/11/2025	Aceite motor - - - ALP EURO, Arandela / tapón cárter - GOMA, Filtro aceite - MECAFILTER, Filtro antipolen- PURFLUX, Líquido lavaparabrisas - CONCENTRADO - Nueva, Serv inspección 1º año, Sustituir Filtro antipolen, Tasa de gestión de aceites usados	2945	BOTIOAUTO S.L.
07/05/2026	Limpiaparabrisas delantero, Limpiaparabrisas trasero	4880	ALVAREZ CUELI SL

Fecha	Descripción	Kilómetros	Taller