APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	VOLKSWAGEN
Model / version:	TAIGO
Vin:	WVGZZZCSZNY041296
Plate:	2CDW897
Mileage:	48180
First registration:	17/06/2022
Color:	Smokey Grey

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES




















































VIN INFORMATION

depuis 04.22
vitres ar teintées foncé
Keyless Entry sans sécurité Safe
rétroviseurs électrique, chauffants et rabattables
rétroviseur int jour/nuit automatique
Soundsystem
phares antibrouillard
caméra de marche arrière "Rear View"

sièges av réglables en hauteur
plancher de chargement modulable

réservoir à charbon actif (EVAP)
capteur de luminosité/capteur de pluie
rétroviseurs avec lampes de projection
caméra av

Infotainment-System (MIB3)
système d'appel d'urgence E-Call
connexion USB
sièges av chauffants

garnissage sièges tissu noir/gris flint
sièges av avec appui lombaire

Climatronic
radio AM/FM
assistant de changement de voie
assistant de trajectoire avec assistant de files
Bluetooth
services Online
assistant au parking
pack Design "Black Style" (seulement pour R-Line)
volant multifonctions en cuir
garniture pavillon noir

avertisseur d'oubli du port des ceintures av/ar	radio avec récepteur numérique	pack Chrome (Type 2)
indicateur multifonctions LCD	accoudoir central av	pédalier Sport
alternateur 140 A	999 cc (1,0 L) 81 KW	6 vitesses
ceintures de sécurité ar avec prétensionneurs	Front Assist/freinage d'urgence City	sélection du profil de conduite (Drive Select)
régulateur de vitesse avec régulation de la distance	215/45 R 18 .. Y	7 J x 18 Alu "Misano" noir
roue de secours acier	protection étendue des piétons avec prévoyance	boulons de roue avec antivol
freins à disque ar 230x9	sidebag avec airbag pour la tête et airbag centraux av	système de sécurité (Pre Crash Basic)
toit ouvrant panoramique	R-Line	norme anti-pollution Euro 6 AP
entretien à intervalle flexible (Long Life)	2 couches nacrée	freins à disque av 276x24
QI6		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm	Semperit	215451893v	All-seasons	Aluminium	×
Front right	6 mm	Semperit	215451893v	All-seasons	Aluminium	×
Rear left	6 mm	Semperit	215451893v	All-seasons	Aluminium	×
Rear right	6 mm	Semperit	215451893v	All-seasons	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Alloy rim FL	Scratch(es)
2	Alloy rim RL	Scratch(es)
3	Bumper R	
3	Bumper moulding R	
5	Wing trim FR	Scratch(es)
6	Alloy rim FR	Scratch(es)

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Wing RR	Dent(s)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Alloy rim FL - Scratch(es)




2 - Alloy rim RL - Scratch(es)




3 - Bumper R




3 - Bumper moulding R





5 - Wing trim FR - Scratch(es)




6 - Alloy rim FR - Scratch(es)




4 - Wing RR - Dent(s) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

27/10/2026 10:32



Customer

27/10/2026 10:32

Useless