



CITROËN C3: 2185-LYB

Vinnumber:	VF7SXYHTUNT536593	Versionname:	Citroen BlueHdi 75KW (100CV) S&S Feel berlina con portón 75kW 5P manual
First Registrationdate:	23/05/2022	Fiscalpower:	
Expertise Mileage:	265262	Power Kw:	
Bodytype:	Berline	Body colour	White
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Steel
Transmission:			
Fueltype:	Diesel		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Luggage cover
Number keys remote	1	
GPS big screen color		
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

205/55/16/91 V				
Summer tyres:	Fr.L.	Goodyear: 7 mm	Fr.R.	Goodyear: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	No
------------	-----------

Registration document, Missing, Repair/replace (lump sum)



Wheel cover RL, Missing, Replace



Door RL, Stone chip(s), Acceptable



Door FL, Scratch(es), Repair and paint (complete)



Wheel cover FL, Missing, Replace



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Paint



Windscreen glue kit, Required to install glazing, Repair/replace (lump sum)



Windscreen, Stone chip(s), Replace



Wheel cover FR, Missing, Replace



Fender moulding FR, Scratch(es), Repair and paint (complete)



Wing FR, Scratch(es), Repair and paint (complete)



Wheel cover RR, Missing, Replace



Tyre repair kit, Missing, Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check



Aerial, Missing, Replace

