APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	NISSAN
Model / version:	JUKE
Vin:	SJNFAAF16U2073652
Plate:	2HCP812
Mileage:	2691
First registration:	03/06/2025
Color:	

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	✓

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?

PICTURES




































VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm		225/45R19 96W	Summer	Aluminium	×
Front right	6 mm		225/45R19 96W	Summer	Aluminium	×
Rear left	6 mm		225/45R19 96W	Summer	Aluminium	×
Rear right	6 mm		225/45R19 96W	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper moulding FR	Grooved
2	Bumper F	Grooved
3	Alloy rim FR polished	Grooved
4	Alloy rim RR polished	Grooved
5	Outside rear-view mirror housing R	Grooved

Total: 5

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
6	Bodywork	Scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Bumper moulding FR - Grooved






2 - Bumper F - Grooved









3 - Alloy rim FR polished - Grooved









4 - Alloy rim RR polished - Grooved







5 - Outside rear-view mirror housing R - Grooved





6 - Bodywork - Scratch(es) - Renta®







SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

16/09/2026 09:49

