



CITROËN BERLINGO: FX-704-NP

Vinnumber:	VR7EFYHYCMN506156	Versionname:	CITROËN BERLINGO M 650kg BlueHDi 100 S&S
First Registrationdate:	2/03/2021		BVM Driver VU [4P] bvm 5-100CH-5cv
Expertise Mileage:	114897		(fourgonnettesimple cabine)
Bodytype:	Transporter	Fiscalpower:	75
Gearbox:	MAN 5 VIT	Power Kw:	
Transmission:	Front	Body colour:	White
Fueltype:	Diesel	Paint type:	Opaque
Engine functioning:	Yes	Interior colour:	Black
Battery functioning:	Yes	Type of rims (mounted):	Steel
Vehicle running:	Yes	Dashboard color:	Black
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Front parking sensors	
GPS big screen color		Rear parking sensors	
Windows electric F		Sliding door right-side	
Cruise Control		Rear view camera	
Steering wheel multifunctional		Seat cover lining	Lining Other
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	195/65/15/91 H			
Summer tyres:	Fr.L.	Michelin: 55%	Fr.R.	Michelin: 55%
	Re.L.	Michelin: 50%	Re.R.	Michelin: 50%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.6
Tyre profile depth RL				4.8
Tyre profile depth RR				4.8
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Runflat	No
-------------	-----	---------	----

Remote ignition key, Missing, Repair/replace (lump sum)



Air vent, mid-dashboard, Broken, Replace



Interior trim, Scratch(es), Smart repair



Gear shift lever cover, Tear, Replace



Interior, Stain, Cleaning



Tyre RR, Tear, Replace



Steel rim RR, Deformed / Strained, Replace



Outside rear-view mirror housing L, Scratch(es), Replace



Side wall RL, Scratch(es), Polish



Sliding door R, Dent(s), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Dent(s), Acceptable



Bumper R, Scratch(es), Acceptable



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FX-704-NP** Date de 1ère immatriculation: **02/03/2021**

Modèle: **Citroen BERLINGO M 650kg BlueHDi 100 S&S BVM Driver VU [4P] bvm 5-100CH-5cv (fourgonnettesimple cabine)**

Date	Kilométrage	Fournisseur	Descriptif
26/11/2025	99.031	SOIRON	REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
28/11/2024	95.013	FLEET SOLUTIONS FRANCE	REMPLACEMENT PNEUS HIVER
31/03/2025	93.631		CONTROLE TECHNIQUE
01/12/2023	82.699	SOCIETE EUROPE AUTO	RECYCLAGE
	0		LAMPE CODE AVD RPLT
	0		REVISION
	0		PLAQUETTES AV RPLT
	0		ADBLUE
	0		BALAISSUIE GLACE AV
31/08/2023	71.988	VIADUC AUTOMOBILES	CAPTEURS DIVERS RPLT
25/05/2023	65.470	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
24/03/2023	60.240	MONDIAL PARE-BRISE	PARE BRISE RPLT
22/02/2023	57.941	SOCIETE EUROPE AUTO	DIVERS ELEC
14/12/2022	52.205	SOCIETE EUROPE AUTO	REVISION ET CLIM ET AIR ET CARBURANT
	0		DISQUES PLAQUETTES AV RPLT
	0		RECYCLAGE
	0		LAMPE CODE AVD RPLT
	0		PLAQUETTES AR RPLT
	0		BALAISSUIE GLACE AV
	0		ADBLUE
	0		COMMANDE DE CLIM RPLT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
14/06/2022	34.229	EUROMASTER FRANCE	REMPLACEMENT PNEUS ETE
28/04/2022	31.061		ADBLUE
	0		REVISION
	0		LIQUIDE LAVE GLACE