

INSPECTION REPORT

End of contract

GENERAL INFO

File	314521
License plate	2BUU333
Vehicle identification number	TMAJE812DNJ088769
Dossier	2021225026
Make	Hyundai Tuc.TGDi PHEV 195kW 4x
Mileage	85765
First registration	30/03/2022
client availability date	12/06/2026
inspectionDate	18/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
104	Door Rear Left // Repair & Painting	N
116	Wing Rear Left // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y

Damage Pictures



Wing Rear Left // Polish-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Door Rear Left // Repair & Painting-scratch + dent