MACADAM









BMW SÃ‰RIE 3 TOURING: GV-734-YZ

Vinnumber:	**WBA11FZ090FS91020**	Versionname:	**BMW SÃ‰RIE 3 TOURING 318d 150ch BVA8 VP [5P] bva 8-150CH-8cv (break)**
First Registrationdate:	**26/03/2024**	Fiscalpower:	
Expertise Mileage:	**140164**	Power Kw:	**110**
Bodytype:	**Break**	Body colour	**White**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**5**		
Number head rests	**5**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		
Last service correctly filled in	**Yes**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Roof bar black	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

	225/50/17/98 V			
Winter tyres:	Fr.L.	**Bridgestone: 50%**	Fr.R.	**Bridgestone: 55%**
	Re.L.	**Bridgestone: 80%**	Re.R.	**Bridgestone: 80%**

Tyre profile depth FL	**4.9**
Tyre profile depth FR	**4.6**
Tyre profile depth RL	**3.0**
Tyre profile depth RR	**3.0**
Tyre size FL	**225/50 R 17 98 V**
Tyre size FR	**225/50 R 17 98 V**
Tyre size RL	**225/50 R 17 98 V**
Tyre size RR	**225/50 R 17 98 V**
Tyre type FL	**Winter**
Tyre type FR	**Winter**
Tyre type RL	**Winter**
Tyre type RR	**Winter**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**255**
Tyre make RR	**255**

Assistance equipment

Runflat	**No**

Seat cover FR, Stain, Cleaning




Tyre FL, Out of tolerance, Replace




Tyre RL, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace




Tyre FR, Out of tolerance, Replace




Door FL, Scratch(es), Polish




Bumper F, Scratch(es), Acceptable




Door RR, Scratch(es), Polish




Wing RR, Scratch(es), Acceptable




Bumper R, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable



ALPHABET

Historique Maintenance

Immatriculation: **GV-734-YZ** Date de 1ère immatriculation: **26/03/2024**

Modèle: **BMW SÉRIE 3 TOURING 318d 150ch BVA8 VP [5P] bva 8-150CH-8cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
25/09/2026	135.664	HORIZON NORMANDIE DIEPPE	REVISION ET CLIM ET AIR ET CARBURANT
31/03/2026	108.968	HORIZON NORMANDIE	DISQUES PLAQUETTES AR RPLT
			SERVICE CONTROLE VH BMW MINI
			REVISION ET CLIM
04/09/2025	90.000	HORIZON NORMANDIE	FILTRE A AIR RPLT
			REVISION ET CLIM
			FILTRE A CARBURANT CTRL
22/08/2025	81.812	HORIZON NORMANDIE	REMPLACEMENT PNEUS HIVER
21/02/2025	52.360	HORIZON NORMANDIE	SERVICE CONTROLE VH BMW MINI
			FILTRE A AIR RPLT
			REVISION ET CLIM
			BALAIS ESSUIE GLACE AV AR
27/09/2024	26.765	HORIZON NORMANDIE	REMPLACEMENT PNEUS HIVER
27/09/2024	26.765	HORIZON NORMANDIE	REFUS
			REVISION ET CLIM