



CITROËN BERLINGO: FB-513-BL

Vinnumber:	VF77B5FK6JJ723111	Versionname:	CITROËN BERLINGO VTi 95 BVM Business M VU [3P] bvm 5-98CH-8cv (fourgonnette-)
First Registrationdate:	15/10/2018	Fiscalpower:	
Expertise Mileage:	64725	Power Kw:	72
Bodytype:	Transporter	Body colour:	White
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Interior colour:	Black
Fueltype:	Petrol	Type of rims (mounted):	Steel
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Type of rims (mounted):	Steel		
Category:	Light Commercial Vehicle		

Options

Number of keys total	1	Radio	
Number keys remote	1	Rear parking sensors	
GPS big screen color		Sliding door right-side	
Windows electric F		Seat cover lining	Lining Other
Cruise Control			
Type of climate control	Manual climate control		

Tyres

	195/65/15/91 T			
Summer tyres:	Fr.L.	Kleber: 25%	Fr.R.	Kleber: 35%
	Re.L.	Kleber: 25%	Re.R.	Kleber: 30%
Tyre profile depth FL				6.4
Tyre profile depth FR				5.9
Tyre profile depth RL				6.4
Tyre profile depth RR				6.1
Tyre size FL				195/65 R 15 91 T
Tyre size FR				195/65 R 15 91 T
Tyre size RL				195/65 R 15 91 T
Tyre size RR				195/65 R 15 91 T
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2479
Tyre make FR				2479
Tyre make RL				2479
Tyre make RR				2479

Assistance equipment

Spare wheel	Yes	Jack	Yes
Remote ignition key, Missing, Repair/replace (lump sum)			



Interior, Dirty, Cleaning



Wheel cover RL, Broken, Replace



Wheel cover FL, Missing, Replace



Wheel cover FR, Missing, Replace



Outer sill L, Dent(s) and scratch(es), Replace and paint



Side panel L, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding FR, Missing, Replace



Grille, Broken, Replace



Bumper F, Broken, Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Replace and paint



Sliding door R, Dent(s) and scratch(es), Repair and paint (complete)



Side wall RR, Dent(s), Repair and paint (complete)



Boot door panel RL, Dent(s) and scratch(es), Repair and paint (complete)



Number plate light R, Broken, Replace



Tailgate handle, Not functioning (well), Check



Boot door panel RR, Dent(s), Repair and paint (complete)



Shutter / cover R, Missing, Replace



Bumper corner RL, Unclamped, Dismount/Mount



Bodywork, Glue residues, Remove lettering



Historique Maintenance

Immatriculation: **FB-513-BL** Date de 1ère immatriculation: **15/10/2018**

Modèle: **Citroen BERLINGO VTi 95 BVM Business M VU [3P] bvm 5-98CH-8cv (fourgonnette-)**

Date	Kilométrage	Fournisseur	Descriptif
20/07/2026	64.658	JOPER AUTO	BATTERIE RPLT
			Pieces
			Main D'œuvre
22/08/2022	59.829	SOCIETE EUROPE AUTO	BATTERIE RPLT
			REPLACEMENT PNEUS ETE
			PARE BRISE RPLT
			DIVERS CLIM
			REVISION ET CLIM ET AIR ET BOUGIES
			BALAIS ESSUIE GLACE AV AR
			DISQUES PLAQUETTES AV RPLT
			PLAQUETTES AR RPLT
			COURROIE ACCESSOIRES RPLT
			RETROVISEUR D RPLT
			ECLAIRAGE DE PLAQUE RPLT
			BATTERIE RPLT
			BATTERIE RPLT
			CONTROLE TECHNIQUE
			RECYCLAGE
			REVISION ET CLIM ET AIR ET BOUGIES
			BATTERIE RPLT
24/09/2019	16.531		LIQUIDE DE FREIN
			REVISION ET CLIM ET AIR ET BOUGIES
			REVISION