




BMW 3 Touring;				
Vinnumber:	WBA6N91060FM45402	Versionname:		
First Registrationdate:	27/01/2022	Fiscalpower:		
Expertise Mileage:	106143	Power Kw:		
Bodytype:		Body colour	Grey	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	3223	
Fueltype:	Hybrid Petrol			
Maintenance	NOT OK			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Options				
Number of keys total	2	Sun Roof electric		
Cruise Control		Panoramic roof		
Steering wheel multifunctional		Luggage cover		
Seats F heated		Front parking sensors		
Radio multimedia		Rear parking sensors		
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible	
Type of GPS	GPS big screen color			
Type of Lining	Lining artificial leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	225/50/16/92 H			
	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 16 92 H
Tyre size FR				225/50 R 16 92 H
Tyre size RL				225/50 R 16 92 H
Tyre size RR				225/50 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260
Assistance equipment				
Number of charging cables (normal)	1			
Number of charging cables (rapid charge)	1			
Total cost ex VAT			604,62	
Service, Maintenance, Check			0,00	



Grille, Crack, Replac

158,83



Bonnet, Scratch(es), Acceptable

0,00



Wing RL, Scratch(es), Acceptable

0,00



Alloy rim RL polished, Rust, Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Rust, Acceptable

0,00





Bumper R, Scratch(es), Acceptable

0,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Rear window, Scratch(es), Replace

0,00



Alloy rim FR polished, Scratch(es), Acceptable

0,00



Wing FR, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RR, Scratch(es), Repair and paint (complete)	445,79
---	--------

