

2-FAW-657


2-FAW-657 · TS 1.8 Hybrid Dynamic + Business pack · 30 June 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-FAW-657	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	SB1ZB3AE70E091255
Model	Corolla	Cylinder Capacity	1.798 ^{cm³}
Model Versions	TS 1.8 Hybrid Dynamic + Business pack	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-03-2024
Color	Silver	Odometer	77.459 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	72	Number Headrests	5

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Electric rear windows	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	Olie verversen over 240 km
Condition interior	Adequate	Last maintenance odometer	61.410
Last Maintenance	23-10-2025	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Rear Left	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Front Right	5 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	16 ^{inch}	Summer
Rear Right	5 ^{mm}	Semperit	205 ^{mm}	55 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Roof

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Left

Small dent(s)

Panelbeating & Spray

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Reardoor - Left

Broken

Raamlijst

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Left

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Left

Dent(s)

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Left

Dent(s)

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Hood

Stonechipping

Acceptable

Yes



Damage Part

Alloy - Right Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Mirror - Rightside

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Alloy - Right Rear

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part

Frontdoor - Right

Damage Type

Scratch(es)

Repair Type

Spray

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Scratch(es)

Spray

No