



BMW 7 Reeks (GKL): CDBA405

Vinnumber:	WBA7D61040CK52480	Versionname:	745e (G11) 3.0i 394pk/cv 4p Aut.
First Registrationdate:	10/06/2022	Fiscalpower:	
Expertise Mileage:	117845	Power Kw:	210
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	3	Type of Tow bar	No Tow bar
GPS			
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/50/18/100 Y			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 2 mm	Re.R.	Bridgestone: 2 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				2.0
Tyre profile depth RR				2.0
Tyre size FL				245/50 R 18 100 Y
Tyre size FR				245/50 R 18 100 Y
Tyre size RL				245/50 R 18 100 Y
Tyre size RR				245/50 R 18 100 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	1		

Seat cover FL, Worn, Acceptable



Backrest cover FL, Worn, Acceptable



Windscreen, Stone chip(s), Acceptable



Charging cable (normal), Missing, Check



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	CDBA405
Merk Model	BMW 745e (G11) 3.0i 394pk/cv 4p Aut.
Brandstofsoort	Benzine
Datum deel1	6/10/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
12/3/25	98,935	batterij	Vervangen
12/3/25	98,935	BMW/MINI service standaard omvang	Uitvoeren
12/3/25	98,935	controle niveaus	Uitvoeren
12/3/25	98,935	klein materiaal	
12/3/25	98,935	service microfilter	Uitvoeren
12/3/25	98,935	service motorolie	Uitvoeren
7/25/25	86,626	klein materiaal	
7/25/25	86,626	ruitenswisserrubber vooraan	Vervangen
4/7/25	79,105	BMW/MINI service standaard omvang	Uitvoeren
4/7/25	79,105	controle niveaus	Uitvoeren
4/7/25	79,105	remvloeistof	Vervangen
11/29/24	65,060	BMW/MINI service standaard omvang	Uitvoeren
11/29/24	65,060	BMW/MINI voertuigcontrole	Uitvoeren
11/29/24	65,060	bougie	Vervangen
11/29/24	65,060	klein materiaal	
11/29/24	65,060	service luchtfilter	Uitvoeren
11/29/24	65,060	service microfilter	Uitvoeren
11/29/24	65,060	service motorolie	Uitvoeren
11/13/23	33,526	controle niveaus	Uitvoeren
11/13/23	33,526	klein materiaal	Uitvoeren
11/13/23	33,526	ruitenswisserrubber vooraan	Vervangen
10/6/23	30,733	klein materiaal	
10/6/23	30,733	service microfilter	Uitvoeren
10/6/23	30,733	service motorolie	Uitvoeren