MACADAM








Peugeot 2008 (UKL): 2EFY199

Vinnumber:	**VR3USHNKKPJ659745**	Versionname:	**2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p**
First Registrationdate:	**28/09/2023**	Fiscalpower:	
Expertise Mileage:	**30622**	Power Kw:	**74**
Bodytype:		Type of rims (mounted)	**Steel**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**9500.0**		
Maintenance	**6 weken**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Steel**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**215/65/16/98 H**			
	Fr.L.	**Continental: 4 mm**	Fr.R.	**Continental: 4 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 4 mm**

Tyre profile depth FL	**4.0**
Tyre profile depth FR	**4.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**4.0**
Tyre size FL	**215/65 R 16 98 H**
Tyre size FR	**215/65 R 16 98 H**
Tyre size RL	**215/65 R 16 98 H**
Tyre size RR	**215/65 R 16 98 H**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Repair kit	**Yes**	Compressor	**Yes**

Floor covering FL, Worn, Acceptable





Interior covering A pillar L, Scratch(es), Smart repair





Door FL, Scratch(es), Spot repair






Central pillar L, Scratch(es), Acceptable




Door RL, Dent(s) and scratch(es), Acceptable







Internal boot lining L, Scratch(es), Smart repair





Rear bulkhead lining, Scratch(es), Acceptable






Boot lid covering R, Scratch(es), Acceptable




Step R, Scratch(es), Acceptable




Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)





Onderhoudshistorie van: VR3USHNKKPJ659745

ALPHABET

Kenteken	2EFY199
Merk Model	Peugeot 2008 Active Pack 1.2 Puretech S&S 100pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	9/28/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
6/4/26	26,974	olie bijvullen	Bijvullen/-laden
11/27/25	20,169	luchtfilter interieur	Vervangen
11/27/25	20,169	oliezeef	Vervangen
11/27/25	20,169	onderhoud 2e jaar	Uitvoeren
11/27/25	20,169	remvloeistof	Vervangen
11/5/24	9,670	luchtfilter interieur	Vervangen
11/5/24	9,670	oliezeef	Vervangen
11/5/24	9,670	onderhoud 1e jaar	Uitvoeren