

INSPECTION REPORT

End of contract

GENERAL INFO

File	314565
License plate	2APX356
Vehicle identification number	WVWZZZ3CZME129370
Dossier	2020323046
Make	Volkswagen Pass.Var.TSI GTE Bu
Mileage	105352
First registration	07/06/2021
client availability date	22/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	N
114	Wing Rear Left // Repair & Painting	N
12	Bumper Front // Smart Repair Large	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	Y
150	Rear Bonnet // Smart Repair Small	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
346	Tyre Front Right // Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
568	Dashboard / Ventilation Outlet / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Front Left // Smart Repair Small-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Dashboard / Ventilation Outlet / Replace-missing




Tyre Front Right // Replace-tear



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-dent




Door Rear Right // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent





Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch




Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch




Light / Rear left / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Smart Repair Large-scratch




Wheel Alloy Front Right // Repair-scratch





Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Door Rear Left // Painting-scratch



Wing Rear Left // Repair & Painting-scratch + dent